



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 1004A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID	BUCKLED	1,028.00	1,028.00
1	BOOT LID LOGO	NECESSARY	42.00	42.00
1	BOOT LID EMBLEM-OPTRA	NECESSARY	32.00	32.00
1	BOOT LID EMBLEM-1.6	NECESSARY	28.00	28.00
1	BOOT LID EMBLEM-CHEVROLET	NECESSARY	32.00	32.00
1	BOOT LID EMBLEM-VGIS	NECESSARY	38.00	38.00
1	BOOT LID EMBLEM-MAGNUM	NECESSARY	40.00	40.00
1	BOOT LID GARNISH	CRACKED	286.00	286.00
1	BOOT LID LOCK	SCRATCHED	68.00	68.00
1	BOOT LID WEATHERSTRIP	NECESSARY	50.00	50.00
2	TAILLAMP ASSY RH & LH @\$285.00	SERVICEABLE	570.00	-
1	REAR BUMPER	DEFORMED	1,360.00	782.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR END PANEL	SERVICEABLE	385.00	-
1	REAR END PANEL TOP COVER	SERVICEABLE	45.00	-
	LESS 10% DISCOUNT		-405.40	-247.60
			3,648.60	2,228.40
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER STICKER-TOP (SN)	NECESSARY	100.00	50.00
1	REVERSE SENSOR (SN)	CUT	200.00	200.00
1	REAR NUMBER PLATE (SN)	SCRATCHED	40.00	35.00
			340.00	285.00
<u>LABOUR</u>				
	TO CUT/WELD REAR END PANEL,KNOCK & STRAIGHTEN REAR BODY MEMBER,REMOVE & REPLACE ACCIDENT DAMAGED PARTS,REALIGN ALL CONNECTION.		700.00	400.00
	SPRAY PAINT BOOT LID,REAR END PANEL,REAR BUMPER,SPARE WHEEL PANEL.		700.00	400.00
	REMOVE & REPLACE LUGGAGE COMPARTMENT INNER TRIM,GARNISH,COVERING.	NOT NECESSARY	60.00	-
	REMOVE & REPLACE REVERSE SENSOR & CHECK FUNCTION.		50.00	40.00

Report Ref No. CS/SMO21000989/R1Ktf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RUST PROOF AFFECTED AREAS.		50.00	30.00
			1,560.00	870.00
GRAND TOTAL			5,548.60	3,383.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CS/SMO21000989/R1Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.