

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000990/GBA3Q2
Date: 15/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800096615
Claimant Vehicle No :	SKP1791D	Insured Vehicle No :	SDL9840Y
Date of Loss:	18/01/2021	Nature of Claim:	TP
		Claim No:	8273966918SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP1791D	Engine No:	2ZRD290026
Make & Model:	TOYOTA PRIUS ALPHA, 1.8 (A)	Chassis No:	ZVW400009083
Reg. Date:	21/08/2014 (Man. Year: 2014)	Odometer:	525199 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,933.66	422.25	3,511.41	89.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	840.00	780.00	48.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,553.66	1,262.25	4,291.41	77.27
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		

Nett Liability (S\$)	1,569.70
Global Sum Settlement (S\$)	1,500.00

INSPECTION

Date of Assignment: 20/01/2021

Date Inspected: 25/01/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Freesion Autodrive (Kaki Bukit)
25 Kaki Bukit Rd 4, Synergy @KB #03-33
Singapore 417800

Adjuster: XING GUO QIANG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	977.00 FL	*523.00 FL
2	2		*REAR BUMPER BRACKETS	Not Necessary	138.00 FL	*- FL
3	1		*REAR BUMPER REFLECTOR	Not Necessary	211.55 FL	*- FL
4	1		*REAR FENDER RH	Repair	1,217.80 FL	*- FL
5	1		*REAR TYRE RIM RH	Repair	1,310.20 FL	*- FL
6	1		*REAR ABSORBER RH	Not Necessary	278.10 FL	*- FL
7	1		*REAR WHEEL BEARING RH	Not Necessary	578.90 FL	*- FL
8	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
9	1		*SET REVERSE SENSOR	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,111.55	553.00
- List Item Discount on L Items 25.00/25.00% (S\$)	1,177.89	130.75
Total Parts (S\$)	3,933.66	422.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	300.00	0.00
2	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	40.00
3	TO PROVIDE LABOUR CHARGES ,WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS ,REPAIR INCLUDING CUT AND WELD ;REALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	600.00	300.00
4	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHARGED BODY PARTS,REPAIR PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	600.00	500.00
Gross Labour Cost (S\$)			1,620.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >