

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21000992/QTD3E2

**Date:** 12/03/2021

### REFERENCE

Insured/Claimant: CHUAN LIM CONSTRUCTION PTE LTD Policy No: DMCVSNW00109722000  
Date of Loss: 11/01/2021 Nature of Claim: OD Claim No: SNM21D200329/C01/CHNGPW

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XE2433K  
Make & Model: SCANIA P360CB6X4MHZ, 12.7 D (M) Engine No: DC13114L016958238  
Reg. Date: 17/11/2016 (Man. Year: 2016) Chassis No: YS2P6X40005434412  
Colour: Multi-colour Odometer: 410848 km  
Engine Capacity: 12742 cc  
Market Value/New Car Price: S\$90,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5  
Front Left Side: Triangle 6 mm Rear Left Side: Triangle 6 mm  
Front Right Side: Triangle 6 mm Rear Right Side: Triangle 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,038.90	14,660.37	14,378.53	49.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,740.00	5,950.00	2,790.00	31.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>37,778.90</b>	<b>20,610.37</b>	<b>17,168.53</b>	<b>45.44</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>16,500.00</b>		
<b>- Excess (S\$)</b>	0.00	2,000.00	-2,000.00	
<b>(S\$)</b>	37,778.90	14,500.00	23,278.90	61.62
<b>+ GST 7.00/7.00% (S\$)</b>	2,644.52	1,015.00	1,629.52	61.62
<b>Nett Amount (S\$)</b>	<b>40,423.42</b>	<b>15,515.00</b>	<b>24,908.42</b>	<b>61.62</b>

### INSPECTION

Date of Assignment: 21/01/2021 Present Location: SC Auto Industries (S) Pte Ltd (HQ)  
Date Inspected: 21/01/2021 Inspected At: SC Auto Industries (S) Pte Ltd (HQ)  
51 Senoko Road, #03-01  
Singapore 758133  
Estimated Period of Repair: 10.0 days

**Adjuster:** OI SUN PIN

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 12 Mar 2021)	
<b>Parts:</b>	N/A	SCANIA P360CB6X4MHZ 12.7 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for XE2433K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR GLASS LHS	Serviceable	420.00 FS	*- FL
2	1		*DOOR HINGE LHS	Bent	684.00 FS	*684.00 FL
3	1		*DOOR LHS ASSY	Crumpled	2,800.00 FS	*2,800.00 FL
4	1		*DOOR TRIM	Serviceable	320.00 FS	*- FL
5	1		*FRONT BUMPER	Crumpled	4,591.99 FS	*2,800.00 FL
6	1		*FRONT CAB CORNER RHS INNER	Missing	40.00 FS	*40.00 FL
7	1		*FRONT CAB CORNER RHS OUTER	Missing	200.00 FS	*200.00 FL
8	1		*FRONT UNDERRUN PROTECTION	Bent	3,965.91 FS	*1,800.00 FL
9	1		*FRONT WINDSCREEN	Cracked	880.00 FS	*880.00 FL
10	1		*FRONT WINDSCREEN PANEL CENTRE	Serviceable	422.28 FS	*- FL
11	1		*FRONT WINDSCREEN PANEL LHS	Crumpled	279.00 FS	*279.00 FL
12	1		*FRONT WINDSCREEN PANEL RHS	Serviceable	279.00 FS	*- FL
13	1		*FRONT WIPER ARM ASSY LHS	Bent	537.45 FS	*377.00 FL
14	1		*FRONT WIPER ARM ASSY RHS	Serviceable	537.45 FS	*- FL
15	1		*FRONT WIPER MOTOR + LINKAGE ASSY	Serviceable	5,248.88 FS	*- FL
16	1		*HEADLAMP ASSY LHS	Crumpled	420.00 FS	*420.00 FL
17	1		*HEADLAMP GUARD LHS	Missing	297.00 FS	*297.00 FL
18	1		*MIRROR DOOR TOP LHS	Cracked	136.00 FS	*136.00 FL
19	1		*MIRROR FRONT 1 LHS	Crumpled	86.00 FS	*86.00 FL
20	1		*MIRROR FRONT 2 LHS	Cracked	86.00 FS	*86.00 FL
21	1		*MIRROR SIDE ASSY LHS	Missing	440.00 FS	*440.00 FL
22	1		*MUDGUARD ASSY LH	Deformed	600.30 FS	*600.30 FL
23	6		*SEALANT	Necessary	294.00 FS	*294.00 FL
24	1		*SIDE CABIN LHS	Dented	1,380.00 FS	*1,380.00 FL
25	1		*STEP ASSY	Crumpled	730.00 FS	*650.00 FL
26	1		*STEP LIGHT	Serviceable	120.00 FS	*- FL
27	1		*SUN VISOR LOWER	Repair	531.36 FS	*- FL
28	1		*SUN VISOR SIGNAL LAMP LHS	Repair	185.40 FS	*- FL
29	1		*SUN VISOR UPPER	Repair	398.16 FS	*- FL
30	1		*UPPER FRONT PANEL GAS SPRING	Bent	408.72 FS	*320.00 FL
31	1		*UPPER FRONT PANEL STRUCTURE (SPACE FRAME)	Crumpled	860.00 FS	*860.00 FL
<b>Supplementary #1</b>						
32	1		*BATTERY COVER ASSY	Crumpled	610.00 FS	*610.00 FL
33	1		*DOOR LOCK ASSY LHS	Jammed	250.00 FS	*250.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>29,038.90</b>	<b>16,289.30</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>1,628.93</b>
<b>Total Parts (\$\$)</b>	<b>29,038.90</b>	<b>14,660.37</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR FRONT & LHS PORTION	New	5,120.00	3,600.00
2	LABOUR FOR WIRING	New	320.00	200.00
3	SPRAY PAINTING	New	2,500.00	1,700.00
4	LABOUR FOR GLASS	New	800.00	450.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,740.00</b>	<b>5,950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >