

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21000993/KVF3Q2

Date: 10/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070115925

Claimant
Vehicle No : CB7008L **Insured Vehicle No :** SDZ9555Y

Date of Loss: 15/01/2021 Nature of Claim: TP Claim No: 3847824829SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	CB7008L		
Make & Model:	TOYOTA HIACE, 3.0 D High-roof 14 Seater (A)	Engine No:	1KD2196179
Reg. Date:	12/09/2012 (Man. Year: 2012)	Chassis No:	JTFST22P100013823
Colour:	Silver	Odometer:	462578 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,194.45	2,389.64	4,804.81	66.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	1,255.00	2,215.00	63.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,664.45	3,644.64	7,019.81	65.82
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	10,664.45	2,900.00	7,764.45	72.81
+ GST 7.00/7.00% (S\$)	746.51	203.00	543.51	72.81
Nett Amount (S\$)	11,410.96	3,103.00	8,307.96	72.81

INSPECTION

Date of Assignment: 21/01/2021

Date Inspected: 25/01/2021 Inspected At:

Yee Auto Pte Ltd (HQ)
160 SIN MING DRIVE, #02-17 SIN
MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	559.50 F	*517.20 FL
2	1		*REAR BUMPER BRACKET-LH	Bent	44.85 F	*44.85 FL
3	1		*REAR BUMPER BRACKET-RH	Bent	44.85 F	*44.85 FL
4	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
5	1		*REAR BUMPER SIDE RETAINER-LH	Serviceable	86.50 F	*- FL
6	1		*REAR BUMPER SIDE RETAINER-RH	Serviceable	86.50 F	*- FL
7	1		*REAR END PANEL-INNER	Repair	415.95 F	*- FL
8	1		*REAR END PANEL-OUTER	Bent	415.95 F	*415.95 FL
9	1		*REAR END PANEL TOP GARNISH	Serviceable	185.10 F	*- FL
10	1		*REAR TAILGATE	Bent	1,982.90 F	*1,982.90 FL
11	1		*REAR TAILGATE CARDBOARD	Serviceable	380.00 F	*- FL
12	1		*SET REAR TAILGATE CARDBOARD CLIPS	Not Necessary	80.00 F	*- FL
13	1		*REAR TAILGATE EMBLEM LOGO	Necessary	99.60 F	*61.10 FL
14	1		*REAR TAILGATE LOCK	Repair	318.15 F	*- FL
15	1		*REAR TAILGATE NUMBER PLATE TOP GARNISH	Serviceable	328.10 F	*- FL
16	1		*REAR TAILGATE REVERSE CAMERA	Serviceable	350.00 F	*- FL
17	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	267.30 F	*- FL
18	1		*REAR TAILLAMP-LH	Serviceable	329.60 F	*- FL
19	1		*REAR TAILLAMP-RH	Serviceable	329.60 F	*- FL
20	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	155.00 F	*- FL
21	1		*REAR BOOT LID STICKER EMERGENCY DOOR	Not Necessary	125.00 FS	*- FS
22	1		*REAR BOOT LID STICKER PULL TO OPEN	Not Necessary	20.00 FS	*- FS
23	1		*REAR NUMBER PLATE	Serviceable	60.00 FS	*- FS
24	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
25	4		*REVERSE SENSORS	Serviceable	400.00 FS	*- FS
26	1		*SPEED LIMIT STICKER 70KM/H	Necessary	20.00 FS	*12.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,194.45	3,168.85
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	779.21
Total Parts (\$)	7,194.45	2,389.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY	New	1,400.00	600.00
2	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,500.00	400.00
3	TO APPLY RUST-PROOFING ON REPAIRED,REPLACED PANEL	New	150.00	60.00
4	TO REMOVE/REFIX REAR WINDSCREEN TO FACILITATE REPAIRS	New	250.00	120.00
5	TO REMOVE/TRANSFER TAILGATE COMPONENTS	New	120.00	60.00
6	TO CHECK WIRING FUNCTIONS	New	50.00	15.00
Gross Labour Cost (\$)			3,470.00	1,255.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >