

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21000995/AGS3Q2
Date: 08/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900102954
Claimant Vehicle No :	SMA93Y	Insured Vehicle No :	SKU2868J
Date of Loss:	23/12/2020	Nature of Claim:	TP
		Claim No:	6400322592SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA93Y		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK051826
Reg. Date:	30/04/2018 (Man. Year: 2017)	Chassis No:	WAUZZZF55JA054195
Colour:	White	Odometer:	49589 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,296.00	8,253.20	6,042.80	42.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,472.00	2,522.00	2,950.00	53.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,768.00	10,775.20	8,992.80	45.49
+ GST 7.00/7.00% (S\$)	1,383.76	754.26	629.50	45.49

Nett Amount (\$\$)	21,151.76	11,529.46	9,622.30	45.49
		+ Loss of Use (4.0 x S\$100.00/day) (\$\$)	400.00	
		+ Doc/Search Fee (\$\$)	2.00	
		Nett Liability (\$\$)	11,931.46	

INSPECTION

Date of Assignment: 28/04/2021

Date Inspected: 28/04/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,251.00 FS	*1,800.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	407.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	228.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE -RH	Not Necessary	63.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	474.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	36.00 FS	*- FS
8	1		*FRONT PARKING AID SENSOR -OUTER	Not Necessary	242.00 FS	*- FS
9	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
10	1		*FRONT FENDER -RH	Repair	1,060.00 FS	*- FS
11	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	53.00 FS	*- FS
12	1		*FRONT FENDER CLOSING ELEMENT -RH	Not Necessary	74.00 FS	*- FS
13	1		*FRONT FENDER BRACKET -RH	Not Necessary	35.00 FS	*- FS
14	1		*FRONT FENDER BRACE -RH	Not Necessary	118.00 FS	*- FS
15	1		*WHEEL HOUSING LINER-RH	Not Necessary	275.00 FS	*- FS
16	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	169.00 FS	*- FS
17	1		*WHEEL SPOILER	Not Necessary	73.00 FS	*- FS
18	1		*WHEEL SPOILER TRIM -RH	Not Necessary	36.00 FS	*- FS
19	1		*STONE CHIP GUARD -RH	Not Necessary	51.00 FS	*- FS
20	1		*FRONT FENDER TRIM -RH	Necessary	164.00 FS	*130.80 FS
21	1		*TOP FENDER LEDGE COVER -UPPER	Not Necessary	36.00 FS	*- FS
22	1		*TOP FENDER LEDGE COVER -LOWER	Not Necessary	16.00 FS	*- FS
23	1		*LED HEADLIGHT -RH	Cut	7,902.00 FS	*6,321.60 FS
24	1		*LIFT CYLINDER RH	Not Necessary	198.00 FS	*- FS
25	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS
					Total Parts (S\$)	14,296.00
						8,253.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE CHECK AND TRANSFER RONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTAL ALL PARTS REMOVED	New	2,400.00	500.00
4	TO RESPRAY REAR BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,472.00	2,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >