

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21000997/T1TF3E2

**Date:** 17/03/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070013391
<b>Claimant Vehicle No :</b>	FBH9662P	<b>Insured Vehicle No :</b>	SJX1811A
Date of Loss:	16/01/2021	Nature of Claim:	TP
		Claim No:	5149828201SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBH9662P	Engine No:	21CG028519
Make & Model:	YAMAHA FZ16, 153cc (M)	Chassis No:	ME121C0G9D2028576
Reg. Date:	27/11/2013 (Man. Year: 2013)	Odometer:	99999 km
Colour:	Black		
Engine Capacity:	153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	110-70 R17	Rear Tyre Size:	150-60 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Metzeler 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	21/01/2021	
Date Inspected:	21/01/2021	Inspected At: Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb Singapore 417800
Estimated Period of Repair:	6.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Cut	0.00 F	*- F
2	1		*FRONT RIM	* Check	0.00 F	*- F
3	1		*FRONT RIM SHAFT	Dented	0.00 F	*- F
4	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
5	1		*FRONT BRAKE DISC	* Check	0.00 F	*- F
6	1		*FRONT FORK ASSY	* Check	0.00 F	*- F
7	1		*FRONT HEADLAMP	Cut	0.00 F	*- F
8	1		*FRONT HEADLAMP TOP GARNISH	Cut	0.00 F	*- F
9	1		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F
10	1		*FRONT WING MIRROR	Cut	0.00 F	*- F
11	1		*FRONT RH SIGNAL LAMP	Cut	0.00 F	*- F
12	1		*METER ASSY	* Check	0.00 F	*- F
13	1		*STEERING CONE & BEARING	Necessary	0.00 F	*- F
14	1		*HANDLE BAR	Bent	0.00 F	*- F
15	1		*HANDLE BAR GRIP	Torn	0.00 F	*- F
16	1		*HANDLE BAR BALANCER RH	Missing	0.00 F	*- F
17	1		*FUEL TANK	Repair	0.00 F	*- F
18	1		*BRAKE RESERVOIR	Cut	0.00 F	*- F
19	1		*HAND BRAKE LEVER	Broken	0.00 F	*- F
20	1		*SIDE FAIRING RH	Cut	0.00 F	*- F
21	1		*REAR FAIRING RH	Cut	0.00 F	*- F
22	1		*FOOT BRAKE	Dented	0.00 F	*- F
23	1		*FRONT FOOT REST	Dented	0.00 F	*- F
24	1		*EXHAUST MUFFLER ASSY	Dented	0.00 F	*- F
25	1		*REAR RIM	* Check	0.00 F	*- F
26	1		*REAR FENDER MUDFLAP	Deformed	0.00 F	*- F
27	1		*REAR SUB FRAME	* Check	0.00 F	*- F
28	1		*REAR RH SIGNAL LAMP	Cut	0.00 F	*- F
29	1		*REAR TAILLAMP	Cut	0.00 F	*- F
30	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
31	1		*REAR BOX	Cut	0.00 F	*- F
32	1		*REAR BOX BRACKET	* Check	0.00 F	*- F
33	1		*REAR REFLECTOR	Cut	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >