

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21001000/KTD3Q2

Date: 10/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070169725
Claimant
Vehicle No : SMM5243K **Insured Vehicle No :** SMW8012M
Date of Loss: 19/01/2021 **Nature of Claim:** TP **Claim No:** 5043461275SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM5243K**
 Make & Model: TOYOTA NOAH, 2.0 (A) Engine No: 2ZR0D65718
 Reg. Date: 01/07/2019 (Man. Year: 2019) Chassis No: ZWR800387259
 Colour: Metallic Maroon Odometer: 84158 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 7 mm
 Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,745.15	1,792.70	1,952.45	52.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	1,160.00	520.00	30.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,425.15	2,952.70	2,472.45	45.57
Approved Total (Overridden) (S\$)		2,350.00		
Nett Amount (S\$)	5,425.15	2,350.00	3,075.15	56.68

INSPECTION

Date of Assignment: 21/01/2021
 Date Inspected: 25/01/2021 Inspected At: BLK 5038 ANG MO KIO INDUSTRIAL PARK 2,
 #01-405
 SINGAPORE 569541
 REPAIRER: LIAN HER MOTORS
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR O/S FENDER	Repair	1,850.90 FL	*- FL
2	1		*REAR BUMPER	Mtg Cracked	1,550.70 FL	*1,025.00 FL
3	1		*REAR O/S BUMPER SIDE RETAINER	Distorted	103.10 FL	*103.10 FL
4	1		*O/S ROCKER PANEL GARNISH	Cracked/Dented	755.50 FL	*755.50 FL
5	1		*REAR N/S TYRE RIM	Dented	550.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,810.20	2,263.60
- List Item Discount on L Items 25.00/25.00% (S\$)	1,065.05	470.90

Total Parts (S\$)	3,745.15	1,792.70
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING & CUTTING	New	700.00	500.00
2	TO PUTTY & SPRAY PAINT REAR ACCIDENT AFFECTED PORTION	New	800.00	600.00
3	DIAGNOSTIC CHECK ON REAR O/S UNDERCARRIAGES AND TO REALIGN WHEEL ALIGNMENT	New	180.00	60.00
Gross Labour Cost (\$\$)			1,680.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >