



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2102979

INV Date 29/04/2021

Reference CC4/LPC21001009/Kbs3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SGM 9007X

Insured Veh. XD 3677Y

Claim No. 20/21/21/VC05/024143

Policy No. Z20VC05005536

Accident Date 13/01/2021

Inspection Date 21/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21001009/Kbs3q2 Date: 29/04/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 3677Y	Veh. Inspected	SGM 9007X	
Policy No.	Z20VC05005536	Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024143	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	21/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	MR053ZEC107133660	Colour	METALLIC GREY	
Odometer	381968 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	MICHELIN	5 mm	
L/H Front Tyre	185/70 R14	MICHELIN	5 mm	
R/H Rear Tyre	185/70 R14	HANKOOK	4 mm	
L/H Rear Tyre	185/70 R14	HANKOOK	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/01/2021	Inspection Date	21/01/2021	
Survey held at	NGS AUTOMOTIVE 10 ANG MO KIO INDUSTRIAL PARK 2A #02-01 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGM 9007X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED / DENTED	326.44	326.44
1	RETAINER SIDE RH	DISTORTED	18.32	18.32
1	PANEL ,REAR SIDE RH	BENT	39.28	39.28
1	FENDER ,REAR RH	BENT	749.15	749.15
1	TAILLAMP RH	MTG CRACKED	279.02	279.02
1	TAILLAMP GASKET RH	NECESSARY	31.58	31.58
1	GARNISH ,TAILLAMP LOWER PANEL RH	BENT	74.90	74.90
	LESS 25% DISCOUNT		-379.67	-379.67
			1,139.02	1,139.02
	<u>SPECIAL NETT ITEMS</u>			
10	CLIPS ,TAILLAMP RH @\$5.00 (SN)	NECESSARY (4 PCS ONLY)	50.00	20.00
1	SEALANT (SN)	NECESSARY	60.00	40.00
			110.00	60.00
	<u>LABOUR</u>			
	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT/ATTACHMENT STRAIGHTEN CHASSIS MEMBER ,CUT & WELD PANEL ,REPAIR /RESHAPE DENTED BODY PANEL,REPLACE DAMAGED PARTS ,REFIT INTO POSITION .		1,200.00	650.00
	TO REMOVE & REPLACE REAR WINDSCREEN .		250.00	120.00
	TO SPRAY PAINTING .		800.00	680.00
	CHECK WIRING /PROPER FUNCTION ON LIGHTS AND ETC.		50.00	20.00
			2,300.00	1,470.00
	GRAND TOTAL		3,549.02	2,669.02



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00
---	--	--	-----------------

Report Ref No. CC4/LPC21001009/Kbs3q2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGM 9007X

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

