

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19013024/R1VF3E2-1

Date: 16/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30129819033
Claimant Vehicle No :	FBA1410P	Insured Vehicle No :	SDZ3810A
Date of Loss:	17/07/2019	Nature of Claim:	TP
		Claim No:	SNM19D203385C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBA1410P	Engine No:	NF125MTE0016025
Make & Model:	HONDA WAVE 125-S, 125cc	Chassis No:	NF125MT0016025
Reg. Date:	13/02/2006 (Man. Year: 2005)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/90-17	Rear Tyre Size:	80/90-17
Front Left Side:	Maxxis 3 mm	Rear Left Side:	Maxxis 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,191.30	1,406.00	5,785.30	80.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	480.00	750.00	60.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,421.30	1,886.00	6,535.30	77.60
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	8,421.30	1,500.00	6,921.30	82.19

INSPECTION

Date of Assignment:	23/07/2019	
Date Inspected:	24/07/2019 Inspected At:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Mar 2021)	
Parts:	N/A	HONDA WAVE 125-S 125cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBA1410P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	Cracked	355.00 FL	*180.00 FL
2	1		*HEADLAMP COWLING	Cracked	105.00 FL	*70.00 FL
3	1		*FRONT FENDER	Cracked	135.00 FL	*60.00 FL
4	1		*FORK STEM }	Bent	235.00 FL	*420.00 FL
5	1		*FORK WHEEL BEARING }	Necessary	183.20 FL	*- FL
6	1		*FORK ASSY }	Bent	575.00 FL	*- FL
7	1		*FRONT BRAKE DISC	Serviceable	185.00 FL	*- FL
8	1		*CLUSTER METER	Serviceable	475.00 FL	*- FL
9	1		*HANDLEBAR	Serviceable	265.80 FL	*- FL
10	1		*HANDLEBAR STEM	Serviceable	375.00 FL	*- FL
11	1		*SET HANDLEBAR GRIP	Serviceable	75.00 FL	*- FL
12	1		*SET HANDLE BAR BALANCER	Serviceable	75.00 FL	*- FL
13	1		*CLUTCH LEVER	Serviceable	75.00 FL	*- FL
14	1		*CLUTCH HOUSING	Serviceable	125.00 FL	*- FL
15	1		*BRAKE LEVER	Serviceable	75.00 FL	*- FL
16	2		*SET SIGNAL LIGHT F	Serviceable	140.00 FL	*- FL
17	2		*SET SIGNAL LIGHT B	Serviceable	140.00 FL	*- FL
18	1		*RADIATOR	Serviceable	425.60 FL	*- FL
19	1		*FRONT UPPER MIDDLE FAIRING }	Scratched	135.00 FL	*340.00 FL
20	1		*FRONT LOWER MIDDLE FAIRING }	Scratched	135.00 FL	*- FL
21	1		*FRONT LEFT FAIRING }	Scratched	135.00 FL	*- FL
22	1		*MIDDLE LEFT FAIRING }	Scratched	135.00 FL	*- FL
23	1		*REAR LEFT FAIRING	Serviceable	135.00 FL	*- FL
24	1		*FRONT RIGHT FAIRING }	Scratched	135.00 FL	*170.00 FL
25	1		*MIDDLE RIGHT FAIRING }	Scratched	135.00 FL	*- FL
26	1		*REAR RIGHT FAIRING	Serviceable	135.00 FL	*- FL
27	2		*PILLION FOOT REST L+R	Serviceable	87.00 FL	*- FL
28	2		*PILLION BRACKET L+R	Serviceable	135.40 FL	*- FL
29	1		*CHAIN COVER	Serviceable	125.00 FL	*- FL
30	1		*EXHAUST ASSY	Serviceable	578.00 FL	*- FL
31	1		*EXHAUST GUARD	Serviceable	165.00 FL	*- FL
32	2		*LICENSE PLATE F+B	Necessary / Bent	60.00 FS	*40.00 FS
33	1		*PHONE CARRIER	Not Necessary	55.00 FS	*- FS
34	1		*IU UNIT	Not Necessary	180.80 FS	*- FS
35	1		*BASKET	Deformed	75.00 FS	*30.00 FS
36	1		*FRONT RIMS	Serviceable	175.00 FS	*- FS
37	1		*SET SIDE MIRRORS	Scratched	135.00 FS	*70.00 FS
38	1		*TAILBOX	Scratched	275.00 FS	*150.00 FS
39	1		*TAILBOX BRACKET	Serviceable	105.00 FS	*- FS
40	1		*HELMET	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,500.80	1,530.00
- List Item Discount on L Items 5.00/10.00% (\$\$)	309.50	124.00
Total Parts (\$\$)	7,191.30	1,406.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R ACCIDENT DAMAGE PARTS, TO CUT / WELD KNOCK AND REALIGN ACCIDENT AFFECTED AREA	New	600.00	300.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	350.00	100.00
3	ELECTRICAL	New	120.00	30.00
4	TO CHECK WHEEL ALIGNMENT	New	75.00	50.00
5	TO CHECK CHASSIS ALIGNMENT	New	85.00	0.00
Gross Labour Cost (\$\$)			1,230.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >