

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21001018/KPA3Q2
Date: 16/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900086096
Claimant Vehicle No :	SHD9828D	Insured Vehicle No :	SJM5535D
Date of Loss:	17/01/2021	Nature of Claim:	TP
		Claim No:	9614877767SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9828D		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2G76351
Reg. Date:	22/07/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU903091234
Colour:	Metallic Pearl White/Red	Odometer:	41750 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,710.05	2,252.90	5,457.15	70.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	1,340.00	2,660.00	66.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,710.05	3,592.90	8,117.15	69.32
+ GST 7.00/7.00% (S\$)	819.70	251.50	568.20	69.32

Nett Amount (S\$)	12,529.75	3,844.40	8,685.35	69.32
+ Car Rental (5.0 x S\$96.30/day) (S\$)		481.50		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,333.35		
Global Sum Settlement (S\$)		4,250.00		

INSPECTION

Date of Assignment: 19/01/2021

Date Inspected: 19/01/2021

Estimated Period of Repair: 3.0 days

Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FRONT BUMPER	Buckled	521.00 FL	*521.00 FL
2	1		*BRACKET ,FRONT BUMPER SIDE ,RH	Serviceable	59.30 FL	*- FL
3	1		*SUPPORT ,FROTN BUMPER SIDE ,RH	Serviceable	80.10 FL	*- FL
4	1		*LINER ,FRONT FENDER ,RH	Serviceable	202.50 FL	*- FL
5	1		*FENDER SUB-ASSY ,FRONT RH	Bent	977.80 FL	*977.80 FL
6	1		*EMBLEM ,SIDE PANEL RH	Necessary	54.60 FL	*54.60 FL
7	1		*MIRROR ASSY ,OUTER REAR VIEW ,RH	Repair	1,436.60 FL	*- FL
8	1		*PANEL SUB-ASSY ,FRONT DOOR ,RH	Bent	1,300.70 FL	*1,300.70 FL
9	1		*REGULATOR SUB-ASSY ,FRONT DOOR WINDOW RH	Serviceable	238.30 FL	*- FL
10	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,RH	Serviceable	926.00 FL	*- FL
11	1		*WEATHERSTRIP FRONT DOOR RH	Serviceable	231.30 FL	*- FL
12	1		*HINGE ASSY ,FRONT DOOR ,LOWER RH	Repair	110.60 FL	*- FL
13	1		*HINGE ASSY ,FRONT DOOR ,UPPER RH	Repair	97.50 FL	*- FL
14	1		*TAPE ,BLACK OUT ,NO.1 FRT RH	Necessary	13.30 FL	*13.30 FL
15	1		*TAPE ,BLACK OUT ,NO.2 FRT RH	Necessary	43.50 FL	*43.50 FL
16	1		*TAPE ,BLACK OUT ,NO.3 FRT RH	Necessary	26.30 FL	*26.30 FL
17	1		*MOULDING ASSY M,BODY ROCKER PANEL ,RH	Repair	594.80 FL	*- FL
18	1		*FRT BUMPER CLIP	Necessary	65.00 FS	*50.00 FS
19	1		*SET FRONT FENDER CLIP	Not Necessary	65.00 FS	*- FS
20	1		*SET FRONT FENDER LINER CLIP	Not Necessary	75.00 FS	*- FS
21	1		*SET FRONT BUMPER CLIP	Repeated	90.00 FS	*- FS
22	1		*TYRE	Serviceable	350.00 FS	*- FS
23	1		*RIM	Serviceable	1,879.40 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,438.60	2,987.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,728.55	734.30
Total Parts (\$\$)	7,710.05	2,252.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,600.00	500.00
2	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	60.00
3	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	700.00
5	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (S\$)			4,000.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >