



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2102188

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 05/04/2021
Reference CC6/CTI21001024/Ara3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. FBL 2901A
Insured Veh. SMJ 6084L
Claim No. SNM21D200357
Policy No. DMHCSNA00005762000
Accident Date 31/12/2020
Inspection Date 19/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21001024/Ara3q2 Date: 05/04/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMJ 6084L	Veh. Inspected	FBL 2901A	
Policy No.	DMHCSNA00005762000	Coverage (\$)	0.00	
Claim No.	SNM21D200357	Excess (\$)	0.00	
Assign From		Assign Date	19/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB400X	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JH2NC4791EK000407	Colour	RED	
Odometer	107649 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70 R17	PIRELLI	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60 R17	PIRELLI	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/12/2020	Inspection Date	19/01/2021	
Survey held at	POLYMATH GARAGE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-02 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 2901A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR FENDER	DEFORMED	65.00	65.00
1	REAR FENDER REFLECTOR	NOT NECESSARY	20.00	-
2	REAR SIGNAL LAMP @\$95.00	N/S CRACKED	190.00	190.00
1	REAR EXHAUST PIPE	DENTED	760.00	760.00
1	REAR EXHAUST PIPE PROTECTOR	DENTED	85.00	85.00
1	REAR RH FOOTREST	NOT NECESSARY	45.00	-
1	FRONT RH FOOTREST	CUT	65.00	65.00
1	FRONT RH ENGINE COVER	CUT	405.00	405.00
1	FRONT RH LOWER COVER	DEFORMED	55.00	55.00
1	FRONT RH TOP CRASH BAR	BENT	220.00	220.00
1	BALANCER RH	CUT	45.00	45.00
1	HANDLE BAR	NOT NECESSARY	235.00	-
1	CLUTCH LEVER	CRACKED	45.00	45.00
1	FRONT RH WING MIRROR	CUT	85.00	85.00
1	FRONT FENDER	TO REPAIR SEE LABOUR	225.00	-
2	FRONT FORK @\$800.00	N/S BENT	1,600.00	800.00
1	FRONT FORK UNDER BRACKET	NOT NECESSARY	285.00	-
1	STEERING STEM	DAMAGED	160.00	160.00
1	FRONT RH SIGNAL LAMP	CRACKED	95.00	95.00
1	FRONT BRACE DISC	NOT NECESSARY	260.00	-
1	HEADLAMP	NOT NECESSARY	275.00	-
1	HEADLAMP COWLING	NOT NECESSARY	240.00	-
1	FRONT RH FAIRING	CRACKED	305.00	305.00
	LESS 10% DISCOUNT		-576.50	-338.00
			5,188.50	3,042.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	20.00	20.00
1	REAR BOX (SN)	CUT	350.00	200.00
1	SET FRONT FORK OIL (SN)	NECESSARY	30.00	30.00
1	SET FRONT FORK OIL SEAL (SN)	NECESSARY	30.00	30.00

Report Ref No. CC6/CTI21001024/Ara3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET STEERING CONE & BEARING (SN)	DAMAGED	60.00	60.00
1	HONDA STICKER (SN)	NECESSARY	20.00	20.00
			510.00	360.00
	<u>LABOUR</u>			
	LABOUR .INCLUSIVE OF THE REPAIR OF FRONT FENDER .		400.00	200.00
	SPRAY PAINTING .		400.00	200.00
	WIRING .		50.00	30.00
	TO STRAIGHTEN BODY CHASSIS .	NOT NECESSARY	250.00	-
	TOWING FEES.		40.00	40.00
			1,140.00	470.00
GRAND TOTAL			6,838.50	3,872.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CC6/CT121001024/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBL 2901A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBL 2901A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBL 2901A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

