

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG21001026/UVF3Q2

**Date:** 25/02/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100271217

**Claimant**  
**Vehicle No :** SLB6048X **Insured Vehicle No :** GBC2024D

Date of Loss: 20/01/2021 Nature of Claim: TP Claim No: 5461445400SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLB6048X</b>	Engine No:	2ZR1732401
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDGG20W90J003807
Reg. Date:	15/04/2016 (Man. Year: 2016)	Odometer:	110302 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,640.75	4,715.02	4,925.73	51.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,710.00	2,170.00	1,540.00	41.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>13,350.75</b>	<b>6,885.02</b>	<b>6,465.73</b>	<b>48.43</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,500.00</b>		
<b>Nett Amount (\$\$)</b>	<b>13,350.75</b>	<b>5,500.00</b>	<b>7,850.75</b>	<b>58.80</b>

### INSPECTION

Date of Assignment: 21/01/2021

Date Inspected: 22/01/2021 Inspected At: Autobay Pte Ltd (kaki Bukit) (HQ)  
1 KAKI BUKIT AVE 6, #02-11  
Singapore 417883

Estimated Period of Repair: 6.0 days

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	1,557.45 FL	*1,557.45 FL
2	2		*REAR TAILGATE HINGE	Not Necessary	130.40 FL	*- FL
3	2		*REAR TAILGATE DAMPER	Not Necessary	423.00 FL	*- FL
4	1		*REAR TAILGATE STOPPER	Not Necessary	12.90 FL	*- FL
5	1		*REAR TAILGATE RUBBER	Serviceable	370.50 FL	*- FL
6	1		*REAR TAILGATE LOCK	Dented/Shorted	497.37 FL	*497.37 FL
7	1		*REAR TAILGATE LOCK CATCH	Not Necessary	46.50 FL	*- FL
8	1		*REAR TAILGATE INNER PULL HANDLE	Not Necessary	89.95 FL	*- FL
9	1		*REAR TAILGATE INNER TRIM	Deformed/Cracked	485.51 FL	*485.51 FL
10	1		*REAR TAILGATE OUTER CHROME MOULDING	Cracked	383.90 FL	*383.90 FL
11	1		*REAR WINDSCREEN MOULDING	Necessary	186.60 FL	*186.60 FL
12	1		*REAR TAILGATE EMBLEM -VALVE MATIC	Necessary	98.50 FL	*98.50 FL
13	2		*REAR NUMBER PLATE LAMP	Not Necessary	97.30 FL	*- FL
14	1		*REAR TAILGATE OPENING CONTROL SWITCH	Not Necessary	165.20 FL	*- FL
15	1		*REAR TAILLAMP	N/s Cracked	1,142.00 FL	*571.00 FL
16	4		*REAR TAILLAMP SIDE HOLDER CLIP	Not Necessary	31.20 FL	*- FL
17	2		*REAR TAILLAMP PANEL HOUSING	Repair	390.00 FL	*- FL
18	1		*REAR BUMPER	Distorted	895.65 FL	*566.01 FL
19	4		*REAR BUMPER CLIP	Necessary	18.00 FL	*18.00 FL
20	1		*REAR BUMPER REFLECTOR LH/RH	N/s Scratched	171.00 FL	*85.50 FL
21	2		*REAR BUMPER BRACKET LH/RH	Serviceable	137.00 FL	*- FL
22	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	128.86 FL	*- FL
23	1		*REAR EXHAUST	Not Necessary	822.60 FL	*- FL
24	2		*REAR EXHAUST MOULDING	Not Necessary	85.20 FL	*- FL
25	1		*REAR END PANEL	Dented/Bent	475.10 FL	*475.10 FL
26	1		*REAR END PANEL GARNISH	Twisted	218.97 FL	*218.97 FL
27	1		*REAR SPARE WHEEL CARRIER	Not Necessary	335.10 FL	*- FL
28	1		*REAR FLOOR PANEL	Repair	827.55 FL	*- FL
29	1		*REAR FLOOR CARDBOARD HOLDER GARNISH	Not Necessary	216.50 FL	*- FL
30	1		*REAR FLOOR PANEL CARDBOARD	Not Necessary	265.70 FL	*- FL
31	1		*REAR FLOOR PANEL SIDE BOARD LH	Not Necessary	155.10 FL	*- FL
32	1		*REAR ANTENNA SENSOR	Cracked	148.50 FL	*148.50 FL
33	1		*REAR FENDER LOWER SHIELD LH	Not Necessary	124.10 FL	*- FL
34	3		*REAR FENDER LOWER SHIELD CLIP	Not Necessary	13.50 FL	*- FL
35	1		*REAR FENDER INNER TRIM LH	Deformed/Twisted	607.62 FL	*607.62 FL
36	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
37	1		*SET REAR INNER TRIM CLIP	Necessary	65.00 FS	*50.00 FS
38	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	50.00 FS	*- FS
39	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
40	1		*REAR REVERSE CAMERA	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 12,579.33 6,190.03**  
**- List Item Discount on L Items 25.00/25.00% (\$\$) 2,938.58 1,475.01**

**Total Parts (\$\$) 9,640.75 4,715.02**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECKING ELECTRICAL WIRING AND CHECK FUNCTIONS	New	60.00	20.00
2	TO REMOVE AND REFIX REAR WINDSCREEN GLASS	New	200.00	120.00
3	TO TRANSFER REAR TAILGATE PARTS	New	120.00	60.00
4	TO REMOVE,REFIX CUSHION AND INNER TRIM	New	180.00	80.00
5	TO REFIX AND REPLACE REVERSE SENSOR AND REVERSE CAMERA	New	180.00	50.00
6	TO REMOVE AND REFIX REAR EXHAUST BOX/SILENCER AND MOUNTINGS	New	150.00	0.00
7	TO RESPRAY UNDERCOATING/RUST PROOFING	New	120.00	60.00
8	TO RESPRAY PAINTING & ETC	New	1,300.00	800.00
9	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	1,400.00	980.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,710.00</b>	<b>2,170.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >