



24 Peshurst Place, Singapore 556440  
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## INVOICE

Seow Wei Ling  
C/o: Jementah Motor Works  
Blk 14 Defu Lane 10  
#01-406 Singapore 539195

Invoice No: CL/200559

Ref No: JMW/11/2002/TP

Date: 18 November 2020

| DESCRIPTION                                                                                                                                                                                                                                                                                  | AMOUNT            |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|
| <b>OUR SERVICE FEE CHARGES:</b> <ul style="list-style-type: none"><li>SURVEY INSPECTION FOR VEHICLE NO. <u>SKB 8079 E</u></li><li>RESURVEY INSPECTION</li><li>DIGITAL PHOTOGRAPHS SERVICES<br/>(INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)</li><li>TRANSPORTATION</li></ul> |                   |
| <b>GRAND TOTAL</b>                                                                                                                                                                                                                                                                           | <b>S\$ 839.00</b> |

E & O. E

All cheque payment should be "Crossed" and made payable to " C L APPRAISER PTE LTD "

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

## VEHICLE INSPECTION REPORT

To: Seow Wei Ling  
C/o: Jementah Motor Works  
Blk 14 Defu Lane 10  
#01-406 Singapore 539195

Date : 18 November 2020  
Our ref : JMW/11/2002/TP

Accident Date : 07 November 2020  
Inspection Date : 09 November 2020  
Repairer Name : Jementah Motor Works  
Blk 14 Defu Lane 10  
#01-406 Singapore 539195

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

|                 |                     |                 |                  |
|-----------------|---------------------|-----------------|------------------|
| Registration No | : SKB 8079 E        | Year / Capacity | : 2011 / 1997 cc |
| Make / Model    | : Nissan qashqai    | Colour          | : Black          |
| Chassis No      | : SJNFBAJ10U2109539 | Mileage         | : 148204         |
| Engine No       | : MR20015233B       |                 |                  |

### CONDITION OF TYRES

|                | Make       | Size       | Thread Balance | Rim   |
|----------------|------------|------------|----------------|-------|
| Front Nearside | : Yokohama | 225/50 R18 | 5 mm           | Sport |
| Front Offside  | : Yokohama | 225/50 R18 | 5 mm           | Sport |
| Rear Nearside  | : Yokohama | 225/50 R18 | 5 mm           | Sport |
| Rear Offside   | : Yokohama | 225/50 R18 | 5 mm           | Sport |

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: 94 copies

### REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis  
and we have not given authorization and instruction to the repairer to proceed with the repair

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle  
and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 12,200.00** on a contractual basis.

Under normal circumstances, the repair period would be about 9 (Nine) working days.

Vehicle Registration No: SKB 8079 E

Our Ref No: JMW/11/2002/TP

| Qty | Description | Conditions | Repairer's Estimate | Revised Amount |
|-----|-------------|------------|---------------------|----------------|
|-----|-------------|------------|---------------------|----------------|

**SPARE PARTS - LIST ITEMS**

|                                |                                    |           |                     |                     |
|--------------------------------|------------------------------------|-----------|---------------------|---------------------|
| 1                              | Rear tailgate                      | Damage    | \$ 3,542.60         | \$ 3,542.60         |
| 2                              | Rear tailgate dampers              | Intact    | \$ 368.00           |                     |
| 1                              | Rear tailgate inner trim           | Damage    | \$ 331.10           | \$ 331.10           |
| 2                              | Rear tailgate lamps                | Damage    | \$ 390.00           | \$ 390.00           |
| 1                              | Rear tailgate lock                 | Damage    | \$ 165.00           | \$ 165.00           |
| 1                              | Rear tailgate logo                 | Necessary | \$ 55.60            | \$ 55.60            |
| 1                              | Rear tailgate rubber               | Necessary | \$ 300.80           | \$ 300.80           |
| 1                              | Rear tailgate "QASHQAI" emblem     | Necessary | \$ 120.20           | \$ 120.20           |
| 1                              | Rear tailgate "XTRONIC" emblem     | Necessary | \$ 85.00            | \$ 85.00            |
| 1                              | Rear tailgate number plate garnish | Damage    | \$ 272.20           | \$ 272.20           |
| 2                              | Rear taillamps                     | Damage    | \$ 971.20           | \$ 971.20           |
| 1                              | Rear end panel                     | Damage    | \$ 740.90           | \$ 740.90           |
| 1                              | Rear end panel inner garnish       | Damage    | \$ 260.80           | \$ 260.80           |
| 1                              | Rear bumper                        | Damage    | \$ 900.80           | \$ 900.80           |
| 2                              | Rear bumper brackets               | Damage    | \$ 183.40           | \$ 183.40           |
| 2                              | Rear bumper lower brackets         | Damage    | \$ 80.00            | \$ 80.00            |
| 1                              | Rear bumper inner sponge           | Damage    | \$ 200.80           | \$ 200.80           |
| 2                              | Rear bumper reflectors             | Intact    | \$ 260.40           |                     |
| 1                              | Rear bumper reinforcement          | Damage    | \$ 450.30           | \$ 450.30           |
| 2                              | Rear bumper side retainers         | Necessary | \$ 140.40           | \$ 140.40           |
| 1                              | Rear bumper tow hook cover         | Damage    | \$ 90.30            | \$ 90.30            |
| 1                              | Rear n/s fender                    | Repair    | \$ 1,547.90         |                     |
| 1                              | Rear floor panel                   | Damage    | \$ 1,883.20         | \$ 1,883.20         |
| 2                              | Rear spare tyre side boards        | Damage    | \$ 570.00           | \$ 570.00           |
|                                |                                    |           | <b>\$ 13,910.90</b> | <b>\$ 11,734.60</b> |
|                                |                                    |           | <i>Less 10%</i>     | <i>\$ 1,391.09</i>  |
| <b>Total Cost - List Items</b> |                                    |           | <b>\$ 12,519.81</b> | <b>\$ 10,561.14</b> |

Vehicle Registration No: SKB 8079 E

Our Ref No: JMW/11/2002/TP

| Qty                         | Description | Conditions | Repairer's Estimate | Revised Amount      |
|-----------------------------|-------------|------------|---------------------|---------------------|
| <b>List Items Total c/f</b> |             |            | <b>\$ 12,519.81</b> | <b>\$ 10,561.14</b> |

**SPECIAL NETT ITEMS**

|                                        |                                 |           |                    |                    |
|----------------------------------------|---------------------------------|-----------|--------------------|--------------------|
| 1                                      | Rear windscreen inner seal      | Necessary | \$ 85.00           | \$ 85.00           |
| 1                                      | Rear windscreen sealant         | Necessary | \$ 80.00           | \$ 50.00           |
| 1                                      | Rear bumper clip (1 set)        | Necessary | \$ 60.00           | \$ 60.00           |
| 1                                      | Rear number plate with holder   | Damage    | \$ 50.00           | \$ 50.00           |
| 1                                      | Rear reverse sensor (1 set)     | Damage    | \$ 350.00          | \$ 350.00          |
| 1                                      | Rear reverse camera             | Damage    | \$ 480.00          | \$ 480.00          |
| 1                                      | Rear spare tyre panel insulator | Necessary | \$ 180.00          | \$ 180.00          |
| <b>Total Cost - Special Nett items</b> |                                 |           | <b>\$ 1,285.00</b> | <b>\$ 1,255.00</b> |

**Total cost of parts**
**\$ 13,804.81 \$ 11,816.14**

Vehicle Registration No: SKB 8079 E

Our Ref No: JMW/11/2002/TP

| S/No                           | Description | Repairer's Estimate | Revised Amount      |
|--------------------------------|-------------|---------------------|---------------------|
| <b>Total cost of parts c/f</b> |             | <b>\$ 13,804.81</b> | <b>\$ 11,816.14</b> |

### **LABOUR**

|   |                                                                                                                                                                          |             |             |
|---|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|-------------|
| 1 | To remove, refit, replaced damaged lamps and check up rear electrical wiring                                                                                             | \$ 80.00    | \$ 50.00    |
| 2 | To remove and refit inner garnishes, inner trim to assist repair.                                                                                                        | \$ 150.00   | \$ 120.00   |
| 3 | To remove and refit rear reverse sensor and camera.                                                                                                                      | \$ 150.00   | \$ 120.00   |
| 4 | To transfer rear tailgate mechanism and wiring assembly to assist repair.                                                                                                | \$ 80.00    | \$ 80.00    |
| 5 | To remove and refit rear windscreen glass.                                                                                                                               | \$ 180.00   | \$ 120.00   |
| 6 | To apply undercoating on repaired and replaced panel.                                                                                                                    | \$ 200.00   | \$ 150.00   |
| 7 | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident. | \$ 1,800.00 | \$ 1,500.00 |
| 8 | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.                                          | \$ 1,600.00 | \$ 1,320.00 |

**GRAND TOTAL**
**\$ 18,044.81    \$ 15,276.14**

Vehicle Registration No: SKB 8079 E

Our Ref No: JMW/11/2002/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 12,200.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

**Disclaimer**

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

**C L APPRAISER PTE LTD**



Cheong K. H  
Automotive Appraiser

24















































