

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001033/BPA3Q2**Date:** 28/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800096051
Claimant Vehicle No :	SKU6099K	Insured Vehicle No :	SMD2779Z
Date of Loss:	19/01/2021	Nature of Claim:	TP
		Claim No:	5625851745SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU6099K		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Engine No:	1ZR521420
Reg. Date:	04/08/2015 (Man. Year: 2015)	Chassis No:	MR053REH104535921
Colour:	Silver	Odometer:	181882 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,700.00	777.00	2,923.00	79.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,170.00	830.00	1,340.00	61.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,870.00	1,607.00	4,263.00	72.62
Approved Total (Overridden) (S\$)		1,250.00		
Nett Amount (S\$)	5,870.00	1,250.00	4,620.00	78.71
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
		(S\$)	1,550.00	
Liabe Amount (50.00%) (S\$)		775.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		782.45		
Global Sum Settlement (S\$)		780.00		

INSPECTION

Date of Assignment:	21/01/2021	
Date Inspected:	21/01/2021 Inspected At:	Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE Singapore 575721
Estimated Period of Repair:	4.0 days	

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	800.00 F	*482.00 FL
2	1		*REAR BUMPER BRACKET RETAINER	Necessary	200.00 F	*158.00 FL
3	1		*REAR BUMPER BOOT PANEL	No Damage	1,200.00 F	*- FL
4	1		*REAR R/H FENDER	Repair	500.00 F	*- FL
5	1		*REAR R/H TYRE MUDFLAP	Cut	250.00 F	*56.00 FL
6	1		*REAR R/H RIMS	Cut	600.00 F	*300.00 FL
7	1		*REAR BUMPER PANEL CLIP	Necessary	150.00 FS	*30.00 FS
					Sub Total (S\$)	3,700.00
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00
					Total Parts (S\$)	777.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIT PANELS	New	600.00	400.00
2	APPLY TUFF KOTE	New	300.00	0.00
3	REMOVE, REFT AND REPLACED DAMAGE AND CHECK UP REAR ELECTRICAL WIRING	New	150.00	30.00
4	REMOVE AND REFIT INNER GARNISHES TRIM TO ASSIST REPAIR	New	200.00	0.00
5	TO APPLY UNDERCOATING ON REPLACED PANEL	New	120.00	0.00
6	TO RESPRAY PAINTING	New	800.00	400.00
Gross Labour Cost (\$)			2,170.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >