

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21001038/QBS3Q2
Date: 30/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900247706
Claimant Vehicle No :	SHD6397A	Insured Vehicle No :	SMQ4399E
Date of Loss:	19/01/2021	Nature of Claim:	TP
		Claim No:	4233818888SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6397A	Engine No:	2ZR2F42154
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU103089381
Reg. Date:	26/12/2019 (Man. Year: 2019)	Odometer:	102000 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,249.02	5,030.02	20,219.00	80.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,766.00	1,380.00	2,386.00	63.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	29,015.02	6,410.02	22,605.00	77.91
	+ Loss of Use (8.5 x S\$50.00/day) (S\$)	425.00		
	+ Car Rental (8.5 x S\$114.49/day) (S\$)	973.17		

+ Doc/Search Fee (S\$)	7.00
Nett Liability (S\$)	7,815.19
Global Sum Settlement (S\$)	7,700.00

INSPECTION

Date of Assignment: 21/01/2021

Date Inspected: 20/01/2021

Estimated Period of Repair: 5.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705**Adjuster:** OI SUN PIN**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CLIPS PIECE FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	45.00 F	*33.75 F
2	1		*COVER FR BUMPER LH (DISC 25%)	Crumpled	30.20 F	*22.65 F
3	1		*BRACKET ,FR BUMPER (DISC 25%)	Crumpled	110.50 F	*82.88 F
4	1		*GRILLE ,RADIATOR (DISC 25%)	Cracked	178.60 F	*133.95 F
5	1		*SUPPORT FR BUMPER RH (DISC 25%)	Broken	80.10 F	*60.08 F
6	1		*SUPPORT FR BUMPER LH (DISC 25%)	Broken	82.30 F	*61.73 F
7	1		*GRILLE SUB-ASSY (DISC 25%)	Crumpled	422.50 F	*316.88 F
8	1		*EMBLEM ASSY FRONT (DISC 25%)	Necessary	105.80 F	*79.35 F
9	1		*EMBLEM SIDE PANEL (HYBRID) (DISC 25%)	Necessary	54.60 F	*40.95 F
10	1		*EMBLEM SIDE PANEL (HYBRID) (DISC 25%)	Necessary	54.60 F	*40.95 F
11	1		*COVER ,FR BUMPER (DISC 25%)	Crumpled	521.00 F	*390.75 F
12	1		*GRILLE RADIATOR (DISC 25%)	Crumpled	178.60 F	*133.95 F
13	1		*SEAL,HOOD TO FR END (DISC 25%)	Cut	85.50 F	*64.13 F
14	1		*MOULDING ,FRONT BUMPER SIDE ,LH (DISC 25%)	Scratched	95.60 F	*71.70 F
15	1		*ABSORBER ,FR BUMPER (DISC 25%)	Crumpled	80.20 F	*60.15 F
16	1		*REINFORCEMENT FRONT UPPER (DISC 25%)	Bent	716.60 F	*537.45 F
17	1		*ABSORBER ,FR BUMPER LOWER (DISC 25%)	Crumpled	132.70 F	*99.53 F
18	1		*GRILLE SUB-ASSY ,2 (DISC 25%)	Crumpled	160.50 F	*120.38 F
19	1		*INLET AIR CLEANER NO.3 (DISC 25%)	Cracked	42.10 F	*31.58 F
20	1		*UNIT HEADLAMP ,LH (DISC 10%)	Crumpled	2,637.60 F	*2,373.84 F
21	1		*LAMP ASSY ,FOG LH (DISC 10%)	Cracked	237.10 F	*213.39 F
22	1		*NUMBER PLATE (SN)	Crumpled	35.00 F	*35.00 F
23	1		*NUMBER PLATE FRAME (SN)	Crumpled	25.00 F	*25.00 F
24	1		*COVER ,FR BUMPER RH	Serviceable	30.20 F	*- F
25	1		*LAMP ASSY ,FOG ,RH	Serviceable	237.10 F	*- F
26	1		*LAMP ASSY ,FOG ,LH	Serviceable	237.10 F	*- F
27	1		*SEAL ,HOOD TO FR END	Serviceable	85.50 F	*- F
28	1		*MOULDING FRONT BUMPER SIDE ,LH	Serviceable	95.60 F	*- F
29	1		*ABSORBER ,FR BUMPER	Serviceable	80.20 F	*- F
30	1		*REINFORCEMENT FRONT UPPER	Serviceable	716.60 F	*- F
31	1		*ABSORBER ,FR BUMPER LOWER	Serviceable	132.70 F	*- F
32	1		*REINFORCEMENT FRONT LOWER	Serviceable	246.10 F	*- F
33	1		*EXTENSION SUB-ASSY RH	Serviceable	120.10 F	*- F
34	1		*EXTENSION SUB-ASSY LH	Serviceable	120.10 F	*- F
35	1		*GRILLE SUB-ASSY ,2	Serviceable	160.50 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*INSULATOR HOOD	Serviceable	410.90 F	*- F
37	1		*HINGE ASSY ,HOOD RH	Serviceable	58.90 F	*- F
38	1		*HINGE ASSY ,HOOD LH	Serviceable	58.90 F	*- F
39	1		*COVER ASSY ENGINE	Serviceable	241.90 F	*- F
40	1		*COVER ,RADIATOR	Serviceable	211.50 F	*- F
41	1		*GUIDE RADIATOR AIR	Serviceable	112.70 F	*- F
42	1		*SEAL ,RADIATOR TO RH	Serviceable	32.60 F	*- F
43	1		*SEAL ,RADIATOR TO LH	Serviceable	32.40 F	*- F
44	1		*GUIDE RADIATOR AIR RH	Serviceable	65.30 F	*- F
45	1		*GUIDE RADIATOR AIR LH	Serviceable	69.90 F	*- F
46	1		*SUPPORT S/A UPPER	Serviceable	377.10 F	*- F
47	1		*SUPPORT SUB-ASSY ,LOWER	Serviceable	409.90 F	*- F
48	1		*BRACE HOOD LOCK SUPPORT	Serviceable	78.30 F	*- F
49	1		*SUPPORT S/A LH	Serviceable	245.10 F	*- F
50	1		*SUPPORT RADIATOR UPPER LH	Serviceable	78.90 F	*- F
51	1		*SUPPORT S/A RH	Serviceable	245.10 F	*- F
52	1		*SUPPORT RADIATOR UPPER RH	Serviceable	78.90 F	*- F
53	1		*UNIT HEADLAMP RH	Serviceable	2,637.60 F	*- F
54	1		*COMPUTER SUB-ASSY HEADLAMP LH NO.1	Serviceable	3,772.50 F	*- F
55	1		*AIR CON CONDENSER ASSY	Serviceable	1,783.20 F	*- F
56	1		*RADIATOR ASSY	Serviceable	2,218.00 F	*- F
57	1		*COOLANT	Serviceable	12.32 F	*- F
58	1		*LINER ,FR FENDER RH	Serviceable	202.50 F	*- F
59	1		*LINER FR FENDER LH	Serviceable	210.30 F	*- F
60	1		*BRACE SUB-ASSY ,FENDER APRON LH	Serviceable	292.10 F	*- F
61	1		*HOOD SUB-ASSY	Repair	983.10 F	*- F
62	1		*FENDER SUB-ASSY ,FR RH	Repair	977.80 F	*- F
63	1		*FENDER SUB-ASSY ,FR LH	Repair	977.80 F	*- F

F=Franchise part.

Total Parts (\$\$)**25,249.02****5,030.02**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	1,014.00	500.00
2	SPRAY PAINT	New	1,872.00	800.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	30.00
5	TO TOP UP A/C GAS	New	120.00	0.00
6	TO REMOVE AND REFIT WIRE HARDESS	New	200.00	20.00
7	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	New	120.00	0.00
8	TO REPLACE SUNDRY PARTS	New	100.00	0.00
9	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			3,766.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >