

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 9114R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOX RH REAR PILLAR (SN)	BUCKLED	800.00	700.00
1	REAR BOX RH LOWER FRAME (SN)	BUCKLED	1,100.00	600.00
			1,900.00	1,300.00
LABOUR				
	TO REMOVE AND REPLACE REAR PILLAR AND LOWER FRAME.		1,600.00	700.00
	TO CARRY OUT ELECTRICAL CHECK.	NOT NECESSARY	60.00	-
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		800.00	300.00
			2,460.00	1,000.00
GRAND TOTAL			4,360.00	2,300.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,850.00
---	--	--	-----------------

Report Ref No. CS3/LPC20011071/R1ff3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.