



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC20011071/R1tf3e2-1	Date: 04/02/2021
			Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XB 9416E		Veh. Inspected	YP 9114R
Policy No.			Coverage (\$)	0.00
Claim No.	20/20/20/VC06/023763		Excess (\$)	0.00
Assign From	KENNY LIM		Assign Date	22/01/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	ISUZU FRR90SUQA-C AMT		c.c	5193
Engine No.	HIDDEN		Year of Reg.	2018
Chassis No.	JALFRR907J7000125		Colour	YELLOW
Odometer	123284 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	FAIR			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/90 R17.5	BRIDGESTONE	7 mm
	L/H Front Tyre	225/90 R17.5	BRIDGESTONE	7 mm
	R/H Rear Tyre	225/90 R17.5 (D)	BRIDGESTONE	7/7 mm
	L/H Rear Tyre	225/90 R17.5 (D)	BRIDGESTONE	7/7 mm
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	12/10/2020		Inspection Date	13/10/2020
Survey held at	R&S ENGINEERING WORKS PTE LTD 13, PIONEER SECTOR 1, SINGAPORE 628424			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	