

6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Claim Reference : -
Insured Vehicle No. : -
Thirty Party Veh No. : -
Officer-In-Charge : -

Our Reference : KAAS/TA/6133/9114/TP/10.20
Invoice No. : 6133
Date : 07 January 2021

To: Vinz Logistics Pte Ltd
c/o No. 13 Pioneer Sector 1
Singapore 628424

INVOICE	
PARTICULARS	AMOUNT
<p>Vehicle No. : YP 9114R Make/Model : Isuzu FRR90SUQA-C AMT</p> <p><input checked="" type="checkbox"/> Inspection of Vehicle</p> <p><input checked="" type="checkbox"/> Appraisal Report</p> <p><input checked="" type="checkbox"/> 24 Colored Photographs</p> <p><input checked="" type="checkbox"/> Transport charges</p> <p><input type="checkbox"/> Re-inspection</p> <p><input type="checkbox"/> Others (Specify)</p>	<p>SGD 364.00</p>
Total	SGD 364.00

Dollars: Three Hundred and Sixty-Four Only

(Cheque should be crossed and make payable to " Kelvin Automotive Appraising Services ")




Kelvin Automotive Appraising Services

FINAL REPAIR INVOICE


INVOICE TO : VINZ LOGISTICS PTE LTD 143 CECIL STREET #03-01 GB BUILDING SINGAPORE 069542			DATE 14/01/2021	INVOICE NO 20200011
DESCRIPTION	Qty	U/P	TAX	AMOUNT
1 TOTAL LUMP SUM REPAIR COST YP9114R	1			\$3,000.00
SUBTOTAL				\$ 3,000.00
TOTAL GST 7%				\$ 210.00
TOTAL AMOUNT DUE SGD				\$ 3,210.00

All cheques must be made payable to "R&S Engineering Works Pte Ltd".

For **R&S Engineering Works Pte.**



(Authorised signature)



kelvin automotive appraising services

6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Claim Reference : -
Insured Vehicle No. : -
Thirty Party Veh No. : -
Officer-In-Charge : -

Our Reference : KAAS/TA/6133/9114/TP/10.20
Date : 07 January 2021

To: Vinz Logistics Pte Ltd
c/o No. 13 Pioneer Sector 1
Singapore 628424

VEHICLE APPRAISAL REPORT

Name of Workshop : R&S Engineering Works Pte Ltd
Place of inspection : No.13 Pioneer Sector 1, Singapore 628424
Date of Assignment : 13 October 2020
Date of Accident : 12 October 2020
Date of Inspection : 13 October 2020

PARTICULARS OF INSPECTED VEHICLE

Registration No.	: YP 9114R	Chassis Frame No.	: JALFRR907J7000125
Make / Model	: Isuzu FRR90SUQA-C AMT	Engine No. (Logcard)	: 4HK1718740
Year of Manufacture/Reg	: 2018	Odometer Reading	: 123,284 KM
Colour	: Yellow		
Class / Type	: Truck		

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)


General Condition : Very Good
Paintwork : Very Good
Market Value : -
Scrap Value : -

CONDITION OF TYRES ON VEHICLE

	<u>Make/Size</u>	<u>Thread Balance</u>
Front L	BRIDGESTONE 225 / 90 R17.5	17 mm
Front R	BRIDGESTONE 225 / 90 R17.5	17 mm
Rear L	BRIDGESTONE 225 / 90 R17.5	17 mm
Rear R	BRIDGESTONE 225 / 90 R17.5	17 mm

*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Our Reference : KAAS/TA/6133/9114/TP/10.20
Vehicle Number : YP 9114R

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		SPECIAL NETT ITEMS:-			
1	1 pc	rear box rh rear pillar	buckled	\$ 800.00	\$ 800.00
2	1 pc	rear box rh lower frame	buckled	\$ 1,100.00	\$ 1,100.00
				\$ 1,900.00	\$ 1,900.00
		LABOUR & OTHER CHARGES:-			
3		To remove and replace rear pillar and lower frame		\$ 1,600.00	\$ 1,200.00
4		To carry out electrical check		\$ 60.00	\$ 50.00
5		To putty and spray-paint of affected areas		\$ 800.00	\$ 600.00
				\$ 2,460.00	\$ 1,850.00
Sub - Total				\$ 4,360.00	\$ 3,750.00

K A A S
kelvin automotive appraising services




6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Our Reference
Vehicle Number

: KAAS/TA/6133/9114/TP/10.20
: YP 9114R

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered **Diagonally to the RH Rear from left to right; rear to front;** portion of the vehicle.



The general area of damages is at the **RH Rear portion**
(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs **R&S Engineering Works Pte Ltd** is \$ **4,360.00** .
We have adjusted the cost to \$ **3,750.00** and the repairer has agreed to undertake the repairs at a
Contract Lump Sum of \$ 3,000.00 to a acceptable quality and standards.
However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of **5** working days.

24 photographs were taken at the time of static inspection.

This report is strictly done in a **Without Prejudice Basis**.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. **6133** for our services rendered and
we thank you for engaging our services.

Conducted By :

Approved By :

TERRENCE HONG
Dip Engineering / DECC (SP)
Certs Automotive Technology (NP)
Cert. Crash Investigation & Reconstruction
Cert SCI (General Insurance)
AMSAAA, AM SAE-A

KELVIN TEO
Licensed Automotive Appraiser
Nitec in Automotive Technology
Cert. Crash Investigation & Reconstruction
Dip MS
MSAAA, AM SAE-A

NOTE : This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.

