

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001047/EVF3E2

Date: 11/02/2021

REFERENCE

Insured/Claimant:	WONG WEI MIN, KEVIN	Policy No:	2070178530		
Date of Loss:	20/01/2021	Nature of Claim:	OD	Claim No:	3319603072SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC2800L	Engine No:	D4HELH262406
Make & Model:	KIA SORENTO, 2.2 (A)	Chassis No:	KNARH81BVM5066335
Reg. Date:	28/12/2020 (Man. Year: 2020)	Odometer:	2279 km
Colour:	Blue		
Engine Capacity:	2151 cc		
Market Value/New Car Price:	S\$158,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,848.40	371.20	3,477.20	90.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	1,210.00	1,150.00	48.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,208.40	1,581.20	4,627.20	74.53
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	5,908.40	1,281.20	4,627.20	78.32
+ GST 7.00/7.00% (S\$)	413.59	89.68	323.91	78.32
Nett Amount (S\$)	6,321.99	1,370.88	4,951.11	78.32

INSPECTION

Date of Assignment:	22/01/2021	
Date Inspected:	26/01/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,528.80 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*BRACKET-FR BUMPER SIDE, RH	* Check	15.00 FL	*- FL
3	1		*BRACKET-FR BUMPER SIDE, LH	* Check	15.00 FL	*- FL
4	1		*STIFFENER ASSY-FR BUMPER LWR	* Check	102.00 FL	*- FL
5	1		*ABSORBER-FRONT BUMPER ENERGY	* Check	117.00 FL	*- FL
6	1		*WIRING HARNESS-FR BUMPER	Not Necessary	371.00 FL	*- FL
7	1		*GRILLE-FRONT BUMPER	Cut	246.00 FL	*246.00 FL
8	1		*COVER-FR BUMPER UPR	Repair	561.00 FL	*- FL
9	1		*GRILLE ASSY-RADIATOR	* Check	575.00 FL	*- FL
10	1		*MOULDING-FRT BPR LICENSE PLATE	Broken	27.00 FL	*27.00 FL
11	1		*REINF ASSY-FR BUMPER, RH	* Check	11.00 FL	*- FL
12	1		*REINF ASSY-FR BUMPER, LH	* Check	11.00 FL	*- FL
13	1		*MOULDING-FRONT BUMPER, RH	Not Necessary	69.00 FL	*- FL
14	1		*MOULDING-FRONT BUMPER, LH	Not Necessary	69.00 FL	*- FL
15	1		*LAMP ASSY-FR FOG, LH	Not Necessary	646.00 FL	*- FL
16	1		*ULTRASONIC SENSOR ASSY - P.A.S	* Check	171.00 FL	*- FL
17	1		*ULTRASONIC SENSOR ASSY - P.A.S	Not Necessary	171.00 FL	*- FL
18	1		*BRKT-RADIATOR GRILLE NO.1	* Check	11.00 FL	*- FL
19	1		*BEAM COMPLETE-FR BUMPER	* Check	883.00 FL	*- FL
20	1		*SKID PLATE-FR BUMPER	Cut	166.00 FL	*166.00 FL
21	1		*PIECE-BUMPER GRILLE	Not Necessary	105.00 FL	*- FL
22	1		*AIR DUCT-FR BUMPER, LH	Not Necessary	28.00 FL	*- FL
23	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	189.00 FL	*- FL
24	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	189.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,798.00	459.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	949.60	87.80
Total Parts (\$\$)	3,848.40	371.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER FACE, FRONT BEAM	New	1,200.00	400.00
2	REMOVE AND INSTALL FRONT PARKING ASSIST	New	60.00	60.00
3	PAINT WORK SPRAY FRONT BUMPER FACE AND AFFECTED PORTION	New	700.00	350.00
4	SUPPLY FRONT NUMBER PLATE WITH FRAME	New	50.00	50.00
5	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT CALIBRATION ON 360 DEGREE CAMERA SETTINGS AFTER REPAIR	New	200.00	200.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (\$\$)			2,360.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >