

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21001048/UBA3Q2
Date: 18/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993662
Claimant Vehicle No :	SKS9931Z	Insured Vehicle No :	SMQ7999D
Date of Loss:	21/01/2021	Nature of Claim:	TP
		Claim No:	5353519519SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS9931Z		
Make & Model:	KIA FORTE K3, 1.6 EX (A)	Engine No:	G4FGFH768342
Reg. Date:	19/05/2015 (Man. Year: 2015)	Chassis No:	KNAFX411MF5404610
Colour:	Grey	Odometer:	80168 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,832.00	5,536.24	6,295.76	53.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,310.00	1,350.00	1,960.00	59.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,142.00	6,886.24	8,255.76	54.52
Approved Total (Overridden) (S\$)		5,500.00		

Adjuster Report

(S\$)	15,142.00	5,500.00	9,642.00	63.68
+ GST 7.00/7.00% (S\$)	1,059.94	385.00	674.94	63.68
Nett Amount (S\$)	16,201.94	5,885.00	10,316.94	63.68
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,292.45		
Global Sum Settlement (S\$)		6,200.00		

INSPECTION

Date of Assignment: 22/01/2021

Date Inspected: 22/01/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	921.00 F	*745.20 FL
2	1		*FRONT BUMPER SIDE RETAINER O/S	Not Necessary	65.00 F	*- FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
4	1		*FRONT BUMPER SPONGE	Torn	215.00 F	*125.50 FL
5	1		*FRONT BUMPER REINFORCEMENT	Serviceable	366.00 F	*- FL
6	1		*FRONT BUMPER FOG LAMP O/S	Cracked	485.00 F	*266.60 FL
7	1		*FRONT BUMPER FOG LAMP GARNISH O/S	Torn	186.00 F	*32.80 FL
8	1		*FRONT FENDER O/S	Dented / Buckled	699.00 F	*699.00 FL
9	1		*FRONT FENDER INNER SHIELD O/S	Torn	282.00 F	*215.30 FL
10	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	50.00 F	*50.00 FL
11	1		*HEADLAMP O/S	Cracked	2,281.00 F	*1,523.00 FL
12	1		*FRONT SUPPORT PANEL	Cracked	715.00 F	*715.00 FL
13	1		*FRONT SHOCK ABSORBER O/S	Serviceable	399.00 F	*- FL
14	1		*FRONT KNUCKLE ARM O/S	Bent	545.00 F	*466.20 FL
15	1		*FRONT KNUCKLE ARM BEARING O/S	Necessary	285.00 F	*199.50 FL
16	1		*FRONT LOWER ARM O/S	Bent	522.00 F	*485.50 FL
17	1		*FRONT DRIVE SHAFT O/S	Not Necessary	1,221.00 F	*- FL
18	1		*FRONT DOOR O/S	Not Necessary	845.00 F	*- FL
19	1		*FRONT SPORT RIM O/S	Cut / Bent	1,500.00 FS	*520.00 FS
20	1		*FRONT TYRE O/S	Not Necessary	200.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,832.00	6,093.60
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	557.36
Total Parts (S\$)	11,832.00	5,536.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	80.00	30.00
3	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
4	TO DISMANTLE & REPLACED FRT UNDER CARRIAGE	New	180.00	120.00
5	TO REFILL AIR CON GAS	New	120.00	100.00
6	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	880.00	600.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	400.00
			Gross Labour Cost (S\$)	3,310.00
				1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >