

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CS/CTI21001053/AVD3N2

Date:

14/12/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

DMPCSNW00142052000

Claimant Vehicle No : SKA9669B**Insured Vehicle No :**

SKH958P

Date of Loss: 18/01/2021

Nature of Claim:

TP

Claim No: SNM21D200314/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKA9669B**

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ2582407

Reg. Date: 07/06/2006 (Man. Year: 2006)

Chassis No: ZNE100308443

Colour: Silver

Odometer: 162519 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size:

205/55R16

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,428.90	1,481.00	947.90	39.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,370.00	1,320.00	2,050.00	60.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,798.90	2,801.00	2,997.90	51.70
Approved Total (Overridden) (S\$)		2,200.00		

Nett Amount (S\$)**5,798.90****2,200.00****3,598.90****62.06**INSPECTION

Date of Assignment: 22/01/2021

Date Inspected: 25/01/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)
13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre
Singapore 417807**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Dec 2021)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA9669B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,012.00 FL	*575.00 FL
2	2		*REAR BUMPER SIDE RETAINER LH & RH	Necessary	143.80 FL	*143.80 FL
3	2		*REAR BUMPER SIDE BRACKET LH & RH	Not Necessary	178.20 FL	*- FL
4	2		*REAR BUMPER REFLECTOR LH & RH	Not Necessary	132.40 FL	*- FL
5	1		*REAR END PANEL	Dented	611.20 FL	*611.20 FL
6	1		*REAR END PANEL TOP GARNISH	Not Necessary	289.60 FL	*- FL
7	1		*REAR TAILGATE WEATHERSTRIP	Cut	258.00 FL	*258.00 FL
8	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
9	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
10	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,085.20	1,878.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	656.30	397.00
Total Parts (\$\$)	2,428.90	1,481.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,400.00	600.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,400.00	600.00
3	TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGE AREAS AND CHECK FOR PROPER FUNCTION	New	150.00	30.00
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	150.00	40.00
5	CAVITY TREATMENT ON NEW PARTS	New	120.00	0.00
6	TO REMOVE AND REPLACE REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (\$\$)			3,370.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >