

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21001056/KQF3E2

Date: 25/02/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00038642002		
Claimant Vehicle No :	PC3036Y	Insured Vehicle No :	GBH4306B		
Date of Loss:	20/01/2021	Nature of Claim:	TP	Claim No:	SNM21D200370/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC3036Y	Engine No:	1KD2414351
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	JTFST22P700020260
Reg. Date:	26/08/2014 (Man. Year: 2014)	Odometer:	454768 km
Colour:	Metallic Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	KAPSEN 9 mm	Rear Left Side:	Delium 9 mm
Front Right Side:	KAPSEN 9 mm	Rear Right Side:	Delium 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,715.63	8,532.79	5,182.84	37.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,240.00	3,880.00	4,360.00	52.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,955.63	12,412.79	9,542.84	43.46
Approved Total (Overridden) (\$\$)		9,900.00		
Nett Amount (\$\$)	21,955.63	9,900.00	12,055.63	54.91

INSPECTION

Date of Assignment:	26/01/2021	Serve You Motor Service (HQ) BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-265 Singapore 569536
Date Inspected:	22/01/2021 Inspected At:	
Estimated Period of Repair:	12.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Feb 2021)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC3036Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE ASSY	Bent	2,054.23 FL	*2,054.23 FL
2	1		*REAR TAILGATE INNER TRIM BOARD	Buckled	428.25 FL	*428.25 FL
3	1		*REAR TAILGATE INNER LOCK	Jammed	359.10 FL	*359.10 FL
4	1		*REAR TAILGATE INNER RUBBER	Serviceable	392.40 FL	*- FL
5	1		*REAR TAILGAIL SHOCK ABSORBER	O/S Punctured	370.00 FL	*185.00 FL
6	1		*REAR RH BODY INNER PILLAR	Bent	750.00 FL	*642.80 FL
7	1		*REAR END PANEL	Bent	654.00 FL	*581.45 FL
8	1		*REAR END PANEL INNER ALUMINIUM TRIM	Serviceable	110.50 FL	*- FL
9	1		*REAR BUMPER	Buckled	372.70 FL	*372.70 FL
10	1		*SET REAR BUMPER BRACKET	Bent	138.00 FL	*69.00 FL
11	1		*REAR TAIL LAMP	Broken	499.40 FL	*354.20 FL
12	1		*REAR RH FENDER	Buckled	1,259.23 FL	*1,259.23 FL
13	1		*SET REAR BUMPER SIDE RETAINER	O/S Distorted	136.00 FL	*68.00 FL
14	1		*SET REAR CORNER PANEL BOTH SIDE	O/S Bent	448.00 FL	*224.00 FL
15	1		*REAR RH CORNER INNER PANEL SIDE COVER	Bent	450.00 FL	*450.00 FL
16	1		*REAR BOARD COVER	Dented	55.00 FL	*55.00 FL
17	1		*FRONT RH DOOR (NPA)	Repair	0.00 FL	*- FL
18	1		*FRONT BUMPER ASSY	Dented	557.00 FL	*523.20 FL
19	1		*FRONT BUMPER RETAINER	Serviceable	88.80 FL	*- FL
20	1		*FRONT LAMP GARNISH	Serviceable	110.40 FL	*- FL
21	1		*FRONT HEAD LAMP	Serviceable	548.00 FL	*- FL
22	4		*REVERSE SENSOR	Dented	480.00 FS	*300.00 FS
23	1		*SCHOOL BUS SILHOUETTE LOGO WITH LIGHTS	Broken	150.00 FS	*80.00 FS
24	1		*TAILGATE EMBLEM 70KM/H	Necessary	50.00 FS	*12.00 FS
25	1		*SET COMPANY LOGO STICKER	Necessary	500.00 FS	*300.00 FS
26	1		*REAR EMERGENCY STICKER	Necessary	30.00 FS	*12.00 FS
27	1		*REAR TAILGATE EMBLEM	Necessary	38.00 FS	*38.00 FS
28	1		*REAR TOYOTA HIACE STICKER	Necessary	84.00 FS	*84.00 FS
29	1		*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS
30	2		*REAR PASSENGER SEAT SUPPORT HOLE	Serviceable	90.00 FS	*- FS
31	1		*REAR WINDSCREEN WIPER	Serviceable	80.00 FS	*- FS
32	1		*REAR WINDSCREEN MOTOR	Serviceable	330.00 FS	*- FS
33	1		*SET REAR PASSENGER SEAT BELT	Cracked	350.00 FS	*350.00 FS
34	1		*REAR PASSENGER SEAT BRACKETS	Repair	220.00 FS	*- FS
35	1		*REAR TAILGATE GLASS	Shattered	1,481.30 FS	*978.60 FS
36	1		*REAR GLASS SEALANT	Necessary	100.00 FS	*40.00 FS
37	1		*REAR PASSENGER DOOR RUBBER	Serviceable	868.00 FS	*- FS
38	1		*REAR RH FENDER SEALANT	Necessary	100.00 FS	*40.00 FS
39	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
40	1		*SEALANT FOR REAR PASSENGER DOOR RUBBER	Not Necessary	750.00 FS	*- FS
41	2		*REAR PASSENGER SEAT (BOTH SIDE) - UPHOLSTERY	Cut	400.00 FS	*400.00 FS
42	1		*REAR FENDER CORNER	Bent	198.10 FL	*198.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,210.41	10,488.86
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,494.78	1,956.07

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (\$)	13,715.63	8,532.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW / KNOCK / STRAIGHTEN THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,500.00	1,300.00
2	TO DISMANTLE, REMOVE AND REFIT TAILGATE GLASS	New	120.00	120.00
3	TO DISMANTLE, REMOVE AND REFIT RH SIDE FENDER GLASS	New	250.00	150.00
4	TO DISMANTLE AND REFIT REAR PASSENGER SEAT (RH) BODY PANEL INNER TRIM BOARD TO FACILITATE REPAIR	New	380.00	200.00
5	TO DISMANTLE, REMOVE AND REFIT REAR TAILGATE TOP SPOILER, THIRD LIGHT, SCHOOL BUS SILHOUETTE LOGO, REAR SPEAKER	New	200.00	80.00
6	TO DISMANTLE, REMOVE AND REFIT REAR SENSOR, CAMERA, WIPER MOTOR AND CHECKING OF WIRING	New	280.00	120.00
7	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY THE AFFECTED AREA REAR RH / PANEL	New	1,500.00	1,100.00
8	LABOUR CHARGE FOR PAINTING ON FRONT DAMAGE PORTION	New	1,200.00	0.00
9	TO DISMANTLE, REMOVE AND REFIT TAILGATE COMPONENT TO REPLACE TAILGATE, CHECK AND RE-ADJUST THE CLOSE GAP AND ALIGNMENT TAILGATE GLASS	New	1,500.00	0.00
10	TO TRANSFER REAR TAILGATE GATE LOCK, MOTOR TO FACILITATE REPAIR WIRING	New	180.00	60.00
11	TO STRAIGHTEN / ALIGN REPAIR / KNOCKING FRONT DAMAGED PORTION AND PARTS	New	480.00	350.00
12	TO TOUCH UP PAINTING ON FRONT DAMAGE PORTION	New	650.00	400.00
Gross Labour Cost (\$\$)			8,240.00	3,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >