Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/AIG21001058/ETF3Q2

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #07-16

Singapore 079120 **Date:** 22/02/2021

REFERENCE

Insured/Claimant: CHUA CHONG SIN Policy No: 1900166352

Date of Loss: 21/01/2021 Nature of Claim: OD Claim No: 2216694743SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKL522S

 Make & Model:
 MITSUBISHI OUTLANDER, 2.0 (A)
 Engine No:
 4J11BG1990

 Reg. Date:
 07/10/2019 (Man. Year: 2019)
 Chassis No:
 GF7W0601792

 Colour:
 Blue
 Odometer:
 12808 km

Engine Capacity: 1998 cc Market Value/New Car Price: \$\$99,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R18 Rear Tyre Size: 225/55R18
Front Left Side: Toyo 5 mm Rear Left Side: Toyo 5 mm
Front Right Side: Toyo 5 mm Rear Right Side: Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,705.45	2,247.61	2,457.84	52.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	2,060.00	900.00	30.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,665.45	4,307.61	3,357.84	43.80
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	7,065.45	3,707.61	3,357.84	47.52
+ GST 7.00/7.00% (S\$)	494.58	259.53	235.05	47.53
Nett Amount (S\$)	7,560.03	3,967.14	3,592.89	47.52

INSPECTION

Date of Assignment: 22/01/2021

Date Inspected: 22/01/2021 Inspected At: Cycle & Carriage Automotive Pte Ltd

(Pandan Gardens) 209 Pandan Gardens Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount			
1	1		*FACE,FR BUMPER	Dented	859.00 FL	*859.00 FL			
2	1		*EXTENSION,FR BUMPER	Not Necessary	515.00 FL	*- FL			
3	1		*BRACKET,FR BUMPER SIDE,LH	Broken	18.00 FL	*18.00 FL			
4	1		*GARNISH,FR BUMPER,LH	Cut	48.00 FL	*48.00 FL			
5	1		*GARNISH,FR BUMPER SIDE	Not Necessary	48.00 FL	*- FL			
6	1		*GARNISH,FR BUMPER SIDE	Not Necessary	220.00 FL	*- FL			
7	1		*GARNISH,FR BUMPER SIDE	Not Necessary	112.00 FL	*- FL			
8	1		*COVER,FR BUMPER	Not Necessary	359.00 FL	*- FL			
9	1		*FENDER,FR LH	Dented	688.00 FL	*688.00 FL			
10	1		*MOULDING,FR BUMPER,LH	Cut	116.00 FL	*116.00 FL			
11	1		*MOULDING,FR WHEEL ARCH,LH	Cut	160.00 FL	*160.00 FL			
12	1		*WHEEL,DISC LHF	Cut	974.00 FL	*974.00 FL			
13	1		*HEADLAMP ASSY,LH	Not Necessary	1,938.00 FL	*- FL			
14	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS			
15	1		*RIVET, FR BUMPER (6PCS) SUPPLEMANTARY	Necessary	30.00 FL	*30.00 FL			
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.								
				Sub Total (S\$)	6,105.00	2,913.00			
	- List Item Discount on L Items 23.00/23.00% (S\$)			1,399.55	665.39				
				Total Parts (S\$)	4,705.45	2,247.61			
	Report was unsubmitted during this print-out.								

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	RENEW FRT BUMPER & LHF FENDER	New	1,800.00	900.00
2	RESPRAY FRT BUMPER & LHF FENDER	New	700.00	700.00
3	RENEW LHF SPORT RIM & TRANSFER TYRE/WHEEL BALANCING	New	30.00	30.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
7	APPLY ZERTONA PAINT PROTECTION ON AFFECTED AREAS	New	160.00	160.00
	Gross Labour Cost (S\$)		2,960.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >