



AIG-00 (REVERT)
SURVEY: 22/01/21
LKK - STEVE

VEHICLE NO : SKL 522 S

MODEL : MIT/OUTLANDER 2.0

WIP : 62185

Material	: \$	<u>2,227.61</u>
Labour	: \$	<u>2,080.00</u>
Sub-Total	: \$	<u>4,307.61</u>
Less 2% Disc	: \$	<u>—</u>
Less Excess	: \$	<u>600.00</u>
Total	: \$	<u>3,707.61</u>
GST 7%	: \$	<u>259.53</u>
Grand Total	: \$	<u>3,967.14</u>

Finalise By/Date : Lanny ON 09/02/21



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 05 WORKING DAYS + 2 days (week end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 26/01/2021	Cust No/Name	KCV12200/CHUA CHONG SIN
	Reg No/Reg Date	SKL522S / 07/10/2019
	Date In/Mileage	26/01/2021/ 19295
	Chassis/Package	GF7W0601792 /DC17P
	Engine No	4J11BG1990
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	D01 COSMIC BLUE MET/ BK BLACK

CYC1

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	08/02/2021/ 11:56	BLE	884 / Lauro Songcuan	62185

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER AND LH FRONT FENDER				900.00 ✓
E PNT98000 SPRAY PAINT FRONT BUMPER & LH FRONT FENDER				700.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				120.00 ✓
M SUNDRY APPLY ZERTONA PAINT PROTECTION ON AFFECTED AREAS				160.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB SUPPLY LABOUR FOR INSTALLATION LH FRONT RIM D/N NO:314321				30.00 ✓
X EXC EXCESS				-600.00
X FACE,FR BUMPER ✓	1.00	859.00	23.00	661.43 ✓
X BRACKET,FR BUMPER SIDE,LH ✓	1.00	18.00	23.00	13.86 ✓
X GARNISH,FR BUMPER,LH ✓	1.00	48.00	23.00	36.96 ✓
X FENDER,FR LH ✓	1.00	688.00	23.00	529.76 ✓
X MOULDING,FR BUMPER,LH ✓	1.00	116.00	23.00	89.32 ✓
X MOULDING,FR WHEEL ARCH,LH ✓	1.00	160.00	23.00	123.20 ✓
X WHEEL,DISC LHF ✓	1.00	974.00	23.00	749.98 ✓
X RIVET,FR BUMPER → <i>Supp</i>	6.00	5.00	23.00	23.10 X
Z TEXT OD CLAIM AIG - REVERT SURVEY: STEVE (LKK) 22.01.2021 DOA: 21.01.2021 05 DAYS <i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	2,227.61	Nett	3,707.61
Labour	1,870.00	7% GST on	259.53
Standard Menu	0.00		
Specialist Job	30.00		
Diagnostics Job	0.00	Total Payable	3,967.14
Sundry/Others	-420.00		
Total(w/o GST)	3,707.61		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SKL 522 S

<u>Material</u>		<u>Cost \$</u>
1	Rivet, FR Bumper (6 pcs)	30.00 ✓ nec
	23% Discount	6.90
		23.10
	7% GST	1.62
	Total	24.72

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SKL5225WIP: 62185 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Rivet Front Bumper	? / SUPP		✓ MC	
2		? / SUPP			
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	29/1/21	Steve
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: OUTLANDERSURVEYOR: STEVE

Work Order: R001337
 License: SKL522S
 Technician: ALVIN (108)
 Mileage: 19295
 Date: 2.2.21 10:05

Mitsubishi : Outlander/Airtrek : 2013- (GF/GG) : Front Wheel Drive

Front : Left

Actual	Before	Specified Range
-0°05'	-0°05'	-0°10' 0°50'
2°10'	2°09'	2°05' 3°05'
0°00'	0°00'	-0°02' 0°06'
14°31'*	14°24'*	11°15' 14°15'
14°26'	14°19'	11°05' 15°05'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°11'	0°11'	-0°10' 0°50'
3°08'*	3°08'*	2°05' 3°05'
0°02'	0°01'	-0°02' 0°06'
13°56'	13°46'	11°15' 14°15'
14°07'	13°57'	11°05' 15°05'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°16'	-0°16'	-0°30' 0°30'
-0°58'*	-0°59'*	-0°30' 0°30'
0°35'	0°38'	
0°01'	0°01'	-0°04' 0°12'

Rear : Left

Actual	Before	Specified Range
-0°44'	-0°44'	-1°15' 0°15'
0°03'	0°03'	0°02' 0°12'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-0°55'	-0°56'	-1°15' 0°15'
0°11'	0°11'	0°02' 0°12'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°12'	0°12'	-0°30' 0°30'
0°15'	0°15'	0°04' 0°24'
-0°04'	-0°04'	

Work Order: R001337
 License: SKL522S
 Technician: ALVIN (108)
 Mileage: 19295
 Date: 2.2.21 10:05

Mitsubishi : Outlander/Airtrek : 2013- (GF/GG) : Front Wheel Drive

Front : Left

Actual	Before	Specified Range
-0°05'	-0°05'	-0°10' 0°50'
2°10'	2°09'	2°05' 3°05'
0°00'	0°00'	-0°02' 0°06'
14°31'*	14°24'*	11°15' 14°15'
14°26'	14°19'	11°05' 15°05'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°11'	0°11'	-0°10' 0°50'
3°08'*	3°08'*	2°05' 3°05'
0°02'	0°01'	-0°02' 0°06'
13°56'	13°46'	11°15' 14°15'
14°07'	13°57'	11°05' 15°05'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°16'	-0°16'	-0°30' 0°30'
-0°58'*	-0°59'*	-0°30' 0°30'
0°35'	0°38'	
0°01'	0°01'	-0°04' 0°12'

Rear : Left

Actual	Before	Specified Range
-0°44'	-0°44'	-1°15' 0°15'
0°03'	0°03'	0°02' 0°12'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-0°55'	-0°56'	-1°15' 0°15'
0°11'	0°11'	0°02' 0°12'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°12'	0°12'	-0°30' 0°30'
0°15'	0°15'	0°04' 0°24'
-0°04'	-0°04'	

All DTCS

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2019MY

SKL5228
Before use, MUST-3x not wait to check all the sound
Just the sound

2021.02.02

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
MP/GDI/DIESEL	GAS_0E640000		No DTCS		
Auto Stop & Go (AS&G)	ASG_25080000		No DTCS		
AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCS		
AUTO CRUISE	GAS_0E640000		Non-target System		
4WS/Electric Power Steering	EPS_45880040		No DTCS		
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCS		
SRS-AIR BAG	ORC_81047302		No DTCS		
Air Conditioner	AC_80080011		No DTCS		
ETACS	ETACS_83040801	B16A2	Turn signal(LH) bulb outage	Active	
Meter	MTR_84084001		No DTCS		
Steering Angle Sensor	GS_SAS_47000100		Non-target System		
AND	AND_8C080002		Non-equipped System or Communication Error		
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error		
LIN	ETACS_83040801		Non-target System		
Power Gate	ETG_92080000		Non-equipped System or Communication Error		

All DTCs

2021.02.02

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
KOS/IMMO/Keyless	KOS_8A880020		No DTCs		
OSS	OSS_9588000B		No DTCs		
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
ACC/FCM	ACCSCFM_4B080000		Non-equipped System or Communication Error		
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
EPB	EPB_4C080000		No DTCs		
Gateway	GW_C1000000		Non-equipped System or Communication Error		
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error		
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2019MY

SKL 5028

after using MUT-3 ver unit to Pass all the hard
as Job Done

2021.02.02

All DTCS

2021.02.02

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
MPI/GDI/DIESEL	GAS_0E640000		No DTCS		
Auto Stop & Go (AS&G)	ASG_25080000		No DTCS		
AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCS		
AUTO CRUISE	GAS_0E640000		Non-target System		
4WS/Electric Power Steering	EPS_45880040		No DTCS		
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCS		
SRS-AIR BAG	ORC_81047302		No DTCS		
Air Conditioner	AC_80080011		No DTCS		
ETACS	ETACS_83040801		No DTCS		
Meter	MTR_84084001		No DTCS		
Steering Angle Sensor	GS_SAS_47000100		Non-target System		
AND	AND_8C080002		Non-equipped System or Communication Error		
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error		
LIN	ETACS_83040801		Non-target System		
Power Gate	ETG_92080000		Non-equipped System or Communication Error		
