### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG21001060/AVF3E2

AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Date: 07/05/2021

**REFERENCE** 

Insured/Claimant: ANDREW TIMOTHY ROBINSON Policy No: 1900121045

Date of Loss: 16/01/2021 Nature of Claim: OD Claim No: 3940379297SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMN210H

Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A) Engine No: CHZC30274

Reg. Date: 18/07/2019 (Man. Year: 2019) Chassis No: WAUZZZ8V5KA080777

Colour: White Odometer: 25816 km

Engine Capacity: 999 cc
Market Value/New Car Price: \$\$97,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,097.00	3,017.36	2,079.64	40.80
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,242.00	1,622.00	2,620.00	61.76
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	9,339.00	4,639.36	4,699.64	50.32
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(S\$)	8,739.00	4,039.36	4,699.64	53.78
	+ GST 7.00/7.00% (S\$)	611.73	282.76	328.97	53.78
	Nett Amount (S\$)	9,350.73	4,322.12	5,028.61	53.78

**INSPECTION** 

Date of Assignment: 22/01/2021

Date Inspected: Premium Automobiles Pte Ltd (UBI)

22/01/2021 Inspected At: 55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH	Dented	2,767.00 FS	*2,213.60 FS
2	1		*FRONT DOOR OUTER SEAL - LH	Necessary	161.00 FS	*128.40 FS
3	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
5	1		*FRONT DOOR CATCH	Not Necessary	105.00 FS	*- FS
6	1		*FRONT EXTERIOR DOOR HANDLE - LH	Missing	374.00 FS	*298.80 FS
7	1		*DOOR HANDLE HOUSING	Cut	52.00 FS	*41.20 FS
8	1		*DOOR HANDLE SLIDE VALVE - LH	Damaged	22.00 FS	*17.28 FS
9	1		*DOOR HANDLE SENSOR	Damaged	228.00 FS	*182.40 FS
10	1		*EXTERIOR DOOR HANDLE MOUNTING BAR	Cracked	162.00 FS	*129.20 FS
11	1		*DOOR HANDLE RELEASE CABLE	Not Necessary	52.00 FS	*- FS
12	1		*SET FRONT DOOR WIRING	Not Necessary	577.00 FS	*-FS
13	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
14	1		*SUNDRIES	Necessary	300.00 FS	*6.48 FS
F=Fra	nchise	part. S=SpcN	lett.	-		
				Total Parts (S\$)	5,097.00	3,017.36
			Report was unsubmitted during	this print-out		

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	350.00	280.00
2	TO DISMANTLE AND RENEW LHS FRONT DOOR. TO REPAIR LHS SILL PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00
3	TO RESPRAY LHS FRONT DOOR, DOOR HANDLE AND LHS SILL PANEL	New	2,300.00	650.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labor	ur Cost (S\$)	4,242.00	1,622.00
	Report was unsubmitted during this	s print-out.		

< END OF ESTIMATES >