

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21001062/AVD3N2**Date:** 15/12/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00197602000

Claimant Vehicle No : SLZ5991C**Insured Vehicle No :** SMR4440M

Date of Loss: 16/01/2021

Nature of Claim: TP

Claim No: SNM21D200285C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLZ5991C**

Make & Model: MAZDA 3, 1.5 (A)

Engine No: PE21056800

Reg. Date: 11/05/2018 (Man. Year: 2017)

Chassis No: JM6BN2278J0204980

Colour: Silver

Odometer: 43424 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18

Rear Tyre Size: 225/40R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,573.35	7,740.16	11,833.19	60.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,270.00	1,670.00	2,600.00	60.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,843.35	9,410.16	14,433.19	60.53
Approved Total (Overridden) (S\$)		7,500.00		
Nett Amount (S\$)	23,843.35	7,500.00	16,343.35	68.54

INSPECTION

Date of Assignment: 22/03/2021

Date Inspected: 21/01/2021 Inspected At:

 Ace Autolution Pte Ltd (KAKI BUKIT)
 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz
 Centre
 Singapore 417807

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Dec 2021)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ5991C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,055.50 FL	*1,055.50 FL
2	1		*FRONT BUMPER SIDE RETAINER LH & RH	O/s Damaged	174.20 FL	*45.00 FL
3	1		*FRONT BUMPER SIGNALLAMP LH & RH	O/s Cracked	839.00 FL	*312.00 FL
4	1		*FRONT BUMPER SIGNALLAMP COVER LH & RH	O/s Deformed	130.60 FL	*65.30 FL
5	1		*FRONT BUMPER SIGNALLAMP WIRELESS LH & RH	O/s Snapped	563.20 FL	*281.60 FL
6	1		*FRONT BUMPER LAMP LH & RH	O/s Cracked	931.60 FL	*465.80 FL
7	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	124.20 FL	*- FL
8	2		*FRONT BUMPER LOWER GRILLE CAP LH & RH	Not Necessary	102.00 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Dented	590.10 FL	*590.10 FL
10	2		*FRONT BUMPER REINFORCEMENT BRACKET LH & RH	Not Necessary	220.40 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT PLATE SET	Not Necessary	120.80 FL	*- FL
12	1		*FRONT GRILLE	Cracked	589.00 FL	*589.00 FL
13	1		*FRONT GRILLE LOGO	Necessary	71.00 FL	*71.00 FL
14	1		*FRONT GRILLE CHROME LH & RH	O/s Cut	353.40 FL	*176.70 FL
15	1		*FRONT GRILLE BRACKET LH & RH	O/s Damaged	70.20 FL	*35.10 FL
16	1		*FRONT GRILLE BRACKET PIN	O/s Cracked	37.80 FL	*18.90 FL
17	2		*FRONT GRILLE BRACKET PIN GROMMET	Necessary	38.20 FL	*38.20 FL
18	1		*FRONT GRILLE UPPER GARNISH	Not Necessary	351.40 FL	*- FL
19	1		*FRONT HEADLAMP LH & RH	O/s Cracked	7,742.00 FL	*3,871.00 FL
20	1		*FRONT HEADLAMP PANEL RH	Not Necessary	355.00 FL	*- FL
21	2		*FRONT HEADLAMP BRACKET LH & RH	Not Necessary	110.80 FL	*- FL
22	1		*FRONT BONNET	Repair	1,259.00 FL	*- FL
23	2		*FRONT BONNET HINGE LH & RH	Not Necessary	162.00 FL	*- FL
24	1		*FRONT BONNET STAY (HOLDER)	Not Necessary	55.00 FL	*- FL
25	1		*FRONT BONNET WEATHERSTRIP (OUTER)	Not Necessary	60.80 FL	*- FL
26	1		*FRONT FENDER LH & RH	O/s Distorted	835.00 FL	*417.50 FL
27	1		*FRONT FENDER INNER SHIELD LH & RH	O/s Deformed	371.00 FL	*185.50 FL
28	1		*FRONT FENDER STAY LH & RH	O/s Bent	303.00 FL	*151.50 FL
29	1		*FRONT FENDER WHEEL HOUSE RH	Repair	786.10 FL	*- FL
30	1		*FRONT SUPPORT PANEL	Not Necessary	477.00 FL	*- FL
31	2		*FRONT SUPPORT PANEL SIDE BRACKET	Not Necessary	116.00 FL	*- FL
32	1		*FRONT UPPER SUPPORT PANEL	Not Necessary	150.00 FL	*- FL
33	1		*FRONT SPARE TANK	Not Necessary	161.20 FL	*- FL
34	1		*FRONT WIPER TANK	Deformed	243.00 FL	*243.00 FL
35	1		*FRONT ENGINE LOWER COVER	Not Necessary	161.00 FL	*- FL
36	1		*FRONT WIPER GARNISH	Not Necessary	321.00 FL	*- FL
37	1		*FRONT BUMPER SENSOR	Damaged	250.00 FL	*250.00 FL
38	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
39	1		*SET FRONT BONNET INSULATOR CLIPS	Not Necessary	100.00 FS	*- FS
40	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	100.00 FS	*30.00 FS
41	1		*COOLANT	Necessary	120.00 FS	*40.00 FS
42	1		*FRONT TYRE RH	Not Necessary	350.00 FS	*- FS
43	1		*FRONT RIM RH	Necessary	550.00 FS	*550.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **21,601.50** **9,512.70**
- List Item Discount on L Items 10.00/20.00% (\$\$) 2,028.15 1,772.54

Report was unsubmitted during this print-out.

12/15/21, 11:41 AM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	19,573.35
						7,740.16
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,800.00	800.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,600.00	600.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	120.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	80.00	60.00
5	TO REMOVE AND REPLACE FRONT DRIVER & PASSENGER AIRBAG	New	220.00	0.00
6	TO CONDUCT WATER SEEPAGE TEST	New	120.00	0.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNIT,RESET MEMORIES TO SPECIFICATION ETC	New	210.00	100.00
8	TO PERFORM WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (\$)			4,270.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >