

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21001063/KBS3Q2
Date: 10/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SHD9820A **Insured Vehicle No :** SLM4793H
Date of Loss: 20/01/2021 Nature of Claim: TP Claim No: MFL2021D0000446

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD9820A**
Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2Z2H41130
Reg. Date: 15/01/2021 (Man. Year: 2020) Chassis No: JTDKB3FU903093338
Colour: Metallic Pearl White/Red Odometer: 1115 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Dunlop 9 mm Rear Left Side: Dunlop 9 mm
Front Right Side: Dunlop 9 mm Rear Right Side: Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,373.50	280.87	2,092.63	88.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,540.00	60.00	4,480.00	98.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,913.50	340.87	6,572.63	95.07
+ GST 7.00/7.00% (\$\$)	483.95	23.86	460.09	95.07
Nett Amount (\$\$)	7,397.45	364.73	7,032.72	95.07
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 22/01/2021
Date Inspected: 22/01/2021 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111
Estimated Period of Repair: 0.5 days

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2021)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9820A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Serviceable	485.60 FL	*- FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
3	1		*GUARD ,REAR BUMPER ,CENTER	Dented / Scratched	374.50 FL	*374.50 FL
4	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	132.60 FL	*- FL
5	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	132.60 FL	*- FL
6	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
7	1		*SET REAR BUMPER CLIP	Not Necessary	85.00 FS	*- FS
8	1		*BUMPER CENTRE GUARD CLIP	Not Necessary	80.00 FS	*- FS
9	1		*REAR BOOT STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
10	1		*REAR BOOT STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
11	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	*- FS
12	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,738.00	374.50
- List Item Discount on L Items 25.00/25.00% (\$)	364.50	93.63
Total Parts (\$)	2,373.50	280.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,600.00	60.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	0.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
Gross Labour Cost (\$\$)			4,540.00	60.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >