

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/III21001073/ABS3Q2

Date:

16/07/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D20MCV0000191_01

Claimant Vehicle No : EN6677A**Insured Vehicle No :**

GBD5993G

Date of Loss: 10/01/2021

Nature of Claim:

TP

Claim No:

MCV2021D0000305

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **EN6677A**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A)

Engine No: 1ZRX535737

Reg. Date: 30/12/2015 (Man. Year: 2015)

Chassis No: MR053REH104541501

Colour: White

Odometer: 79447 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,110.60	7,397.35	4,713.25	38.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	1,950.00	2,090.00	51.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,150.60	9,347.35	6,803.25	42.12
Approved Total (Overridden) (S\$)		7,400.00		

(S\$)	16,150.60	7,400.00	8,750.60	54.18
+ GST 7.00/7.00% (S\$)	1,130.54	518.00	612.54	54.18
Nett Amount (S\$)	17,281.14	7,918.00	9,363.14	54.18
+ Loss of Use (8.0 x S\$80.00/day) (S\$)		640.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,565.45		
Global Sum Settlement (S\$)		8,400.00		

INSPECTION

Date of Assignment: 20/01/2021

Date Inspected: 20/01/2021

Inspected At:

MG Solution Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre
 Singapore 415933

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EN6677A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	1,255.30 FL	*1,140.00 FL
2	2		*BONNET HINGE	Not Necessary	124.60 FL	*- FL
3	1		*BONNET LOCK	Not Necessary	180.20 FL	*- FL
4	1		*BONNET LOCK BRACE PANEL	Not Necessary	120.00 FL	*- FL
5	1		*FRONT BUMPER	Distorted	650.30 FL	*650.30 FL
6	1		*FRONT BUMPER SIDE RETAINER	N/S Damaged	124.80 FL	*62.40 FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	420.00 FL	*374.00 FL
8	1		*FRONT BUMPER REINFORCEMENT SPONGE	Cracked	180.00 FL	*180.00 FL
9	1		*FRONT BUMPER FOGLAMP LH	Missing	420.30 FL	*278.00 FL
10	1		*FRONT BUMPER FOGLAMP HOUSING LH	Missing	155.30 FL	*155.30 FL
11	1		*FRONT BUMPER LOWER GRILLE	Deformed	255.40 FL	*191.00 FL
12	1		*FRONT BUMPER UNDER COVER	Cracked	420.00 FL	*146.00 FL
13	1		*FRONT GRILLE	Cracked	688.70 FL	*399.00 FL
14	1		*FRONT GRILLE LOGO	Necessary	90.00 FL	*60.00 FL
15	1		*FRONT FENDER	N/S Dented	1,160.60 FL	*580.30 FL
16	1		*FRONT FENDER EMBLEM VVT-I	N/S Necessary	120.40 FL	*45.00 FL
17	1		*FRONT FENDER INNER COWLING LH	Torn	266.30 FL	*141.00 FL
18	2		*HORN	Not Necessary	180.00 FL	*- FL
19	2		*HEADLAMP	N/S Smashed / O/S Cracked	3,953.00 FL	*3,953.00 FL
20	1		*HEADLAMP LOWER BRACKET	N/S Cracked	140.00 FL	*30.00 FL
21	1		*FRONT SUPPORT PANEL	Buckled	1,130.50 FL	*899.00 FL
22	1		*FRONT SUPPORT PANEL COVER	Cracked	133.20 FL	*133.20 FL
23	1		*AIR VENT ASSY (CENTRE)	Not Necessary	144.20 FL	*- FL
24	1		*AIR VENT ASSY (BELOW)	Cracked	192.30 FL	*192.30 FL
25	1		*RADIATOR	Not Necessary	1,255.30 FL	*- FL
26	1		*AIR CONDENSOR	Not Necessary	980.20 FL	*- FL
27	1		*FRONT LOWER ARM LH	Not Necessary	354.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT KNUCKLE ARM LH	Not Necessary	232.10 FL	*- FL
29	1		*FRONT KNUCKLE ARM BEARING LH	Not Necessary	187.20 FL	*- FL
30	1		*FRONT SHOCK ABSORBER LH	Not Necessary	326.50 FL	*- FL
31	1		*FRONT NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
32	1		*SET FRONT BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
33	1		*SET FRONT BUMPER UNDER CLIPS	Necessary	20.00 FS	*20.00 FS
34	1		*SET FRONT GRILLE CLIP	Necessary	20.00 FS	*20.00 FS
35	1		*FRONT FENDER COWLING CLIPS	Necessary	20.00 FS	*20.00 FS
36	1		*SET SUPPORT PANEL COVER CLIP	Necessary	20.00 FS	*20.00 FS
37	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
					Sub Total (S\$)	16,070.80
					- List Item Discount on L Items 25.00/25.00% (S\$)	3,960.20
					Total Parts (S\$)	12,110.60
						7,397.35

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,600.00	1,000.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	800.00
3	WIRING CHECK	New	150.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	100.00	60.00
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	350.00	0.00
7	FOUR WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (S\$)			4,040.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >