

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III21001076/DPA3Q2

Date: 16/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MPC0007184
Claimant Vehicle No :	SMG6025Z	Insured Vehicle No :	SJK510T
Date of Loss:	24/12/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0002826

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG6025Z		
Make & Model:	MAZDA 3, 1.5 SEDAN AT LED EU6 (A)	Engine No:	P520567803
Reg. Date:	26/12/2018 (Man. Year: 2018)	Chassis No:	JM6BN22A8K0266698
Colour:	Grey	Odometer:	48256 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,621.90	2,433.10	188.80	7.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,770.00	3,570.00	3,200.00	47.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,391.90	6,003.10	3,388.80	36.08
+ GST 7.00/7.00% (S\$)	657.43	420.22	237.21	36.08
Nett Amount (S\$)	10,049.33	6,423.32	3,626.01	36.08
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
Nett Liability (S\$)		6,663.32		

INSPECTION

Date of Assignment:	21/01/2021		
Date Inspected:	01/02/2021	Inspected At:	Trans Eurokars Pte Ltd (Ubi) 5 Ubi Close Singapore 408605
Estimated Period of Repair:	4.0 days		

Adjuster: BRYAN TANI

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2021)
Parts:	143	MAZDA 3 1.5 SEDAN AT LED EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG6025Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RHS	Dented	1,200.40 F	*1,200.40 F
2	1		*FASTENER ,FRONT DOOR	Necessary	3.20 F	*3.20 F
3	1		*GROMMET ,FRONT DOOR	Not Necessary	2.40 F	*- F
4	1		*CLIP ,FRONT BUMPER	Necessary	2.40 F	*2.40 F
5	8		*GROMMET ,FRONT DOOR	Necessary	24.00 F	*24.00 F
6	1		*GROMMET ,FRONT DOOR	Necessary	3.80 F	*3.80 F
7	1		*REAR DOOR RHS	Dented	1,049.40 F	*1,049.40 F
8	1		*HINGE UPPER RHS ,REAR DOOR	Not Necessary	41.00 F	*- F
9	1		*HINGE LOWER RHS ,REAR DOOR	Not Necessary	44.80 F	*- F
10	1		*FASTENER ,REAR DOOR	Necessary	4.70 F	*4.70 F
11	1		*FASTENER ,REAR DOOR	Necessary	3.20 F	*3.20 F
12	1		*GROMMET ,REAR DOOR	Not Necessary	2.40 F	*- F
13	1		*CLIP ,REAR DOOR	Necessary	2.40 F	*2.40 F
14	7		*GROMMET ,REAR DOOR	Necessary	21.00 F	*21.00 F
15	1		*GROMMET ,REAR DOOR	Necessary	3.80 F	*3.80 F
16	1		*STONE GUARD RHS	Not Necessary	18.20 F	*- F
17	6		*CLIP ,GARNISH -DOOR	Necessary	73.80 F	*73.80 F
18	7		*GROMMET ,SPEAKER	Necessary	21.00 F	*21.00 F
19	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
Total Parts (\$\$)					2,621.90	2,433.10

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT DOOR RH AND REAR DOOR RH REPAIR ROCKER PANEL RH AND ALL AREAS AFFECTED BY THE ACCIDENT	New	2,640.00	1,320.00
2	TO RESPRAY FRONT DOOR RH ,REAR DOOR RH AND ROCKER PANEL RH	New	2,520.00	1,260.00
3	TO TRANSFER THE DOOR MECHANISM (FRONT & REAR)	New	660.00	660.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
5	TO CARRY OUT BODY CAVITY PRESERVATION (INCLUDING NEW PARTS AND CAOUTCHOU)	New	250.00	0.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
7	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP	New	100.00	0.00
Gross Labour Cost (\$\$)			6,770.00	3,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >