

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CC4/ASM21001077/Ags3q2	
	8 SHENTON WAY AXA TOWERSING		Date:	07/07/2021	
	ATTN:KIAN CHUA	N	Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 7042R	Veh. Inspected	SKK 6664G	
	Policy No.	P2419138	Coverage (\$)	0.00	
	Claim No.	S1M0357Q	Excess (\$)	0.00	
	Assign From		Assign Date	20/01/2021	
2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. 320I	c.c	1997	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	WBA3B16050NP58209	Colour	WHITE	
	Odometer	73126 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm	
	L/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm	
	R/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm	
	L/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	19/01/2021	Inspection Date	20/01/2021	
	Survey held at	MG SOLUTION PTE LTD			
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days			
	<u> </u>				