

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001080/EQD3E2

Date: 10/03/2021

REFERENCE

Insured/Claimant:	TOH YAN LING	Policy No:	1900006628		
Date of Loss:	21/01/2021	Nature of Claim:	OD	Claim No:	6002669980SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH3977R		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Engine No:	3A92UHK3324
Reg. Date:	22/01/2019 (Man. Year: 2018)	Chassis No:	MMBSTA13AJH004474
Colour:	Red	Odometer:	34424 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$54,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,714.84	6,484.97	6,229.87	49.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,255.00	5,450.00	1,805.00	24.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,969.84	11,934.97	8,034.87	40.24
+ GST 7.00/7.00% (S\$)	1,397.89	835.45	562.44	40.23
Nett Amount (S\$)	21,367.73	12,770.42	8,597.31	40.24

INSPECTION

Date of Assignment: 22/01/2021

Date Inspected: 22/01/2021 Inspected At:

Estimated Period of Repair: 12.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
2	1		*FENDER, FR RH	Dented	500.00 FL	*500.00 FL
3	1		*EMBLEM ECO	Necessary	17.00 FS	*17.00 FS
4	1		*SHIELD, FR WHEELHOUSE, RH	Crumpled	98.00 FL	*98.00 FL
5	10		*CLIP, FENDERSHIELD	Necessary	40.00 FL	*40.00 FL
6	1		*CROSSMEMBER, FR AXLE, NO.1	Bent	868.00 FL	*868.00 FL
7	1		*ARM ASSY, FR SUSP, LWR RH	Bent	280.00 FL	*280.00 FL
8	1		*STRUT, FR SUSP	Bent	456.00 FL	*456.00 FL
9	1		*DAMPER, FR SUSP STRUT	Necessary	24.00 FL	*24.00 FL
10	1		*PAD, FR SUSP SPRING	Necessary	17.00 FL	*17.00 FL
11	1		*SEAT, FR SUSP SPRING, UPR	Bent	37.00 FL	*37.00 FL
12	1		*BEARING, FR SUSP STRUT	Necessary	9.00 FL	*9.00 FL
13	1		*SUPPORT, FR SUSP STRUT	Not Necessary	17.00 FL	*- FL
14	1		*INSULATOR, FR SUSP STRUT	Necessary	84.00 FL	*84.00 FL
15	1		*INSULATOR, FR SUSP STRUT	Not Necessary	98.00 FL	*- FL
16	1		*GEAR & LINK ASSY, STEERING	Not Necessary	1,444.00 FL	*- FL
17	1		*END ASSY, TIE ROD	Not Necessary	52.00 FL	*- FL
18	1		*HUB ASSY, FR WHEEL	Necessary	242.00 FL	*242.00 FL
19	1		*SNAP RING, FR WHEEL HUB	Necessary	8.00 FL	*8.00 FL
20	1		*BEARING, FR WHEEL HUB	Necessary	122.00 FL	*122.00 FL
21	1		*KNUCKLE, RH	Bent	367.00 FL	*367.00 FL
22	1		*COVER, FR BRAKE DISC	Not Necessary	26.00 FL	*- FL
23	1		*SHAFT AS, FR AXLE DRIVE, RH	Not Necessary	1,201.00 FL	*- FL
24	1		*WHEEL, DISC	Cut	687.00 FL	*687.00 FL
25	1		*BODY KIT, ATTRAGE	Not Necessary	1,643.00 FS	*- FS
26	1		*PANEL, HEADLAMP SUPPORT, UPR	Bent	66.00 FL	*66.00 FL
27	1		*PANEL ASSY, FR END	Dented	1,055.00 FL	*1,055.00 FL
28	1		*CONDENSER ASSY, A/C REFRIGE	Not Necessary	758.00 FL	*- FL
29	1		*PANEL, AIR GUIDE	Not Necessary	112.00 FL	*- FL
30	1		*RADIATOR ASSY	Not Necessary	967.00 FL	*- FL
31	1		*PANEL, AIR GUIDE, RH	Not Necessary	11.00 FL	*- FL
32	1		*PANEL, AIR GUIDE, LH	Not Necessary	11.00 FL	*- FL
33	1		*LLC 4L	Not Necessary	26.00 FL	*- FL
34	1		*COVER, ENG ROOM UNDER, FR	Not Necessary	99.00 FL	*- FL
35	10		*CLIP, FR BUMPER	Necessary	40.00 FL	*40.00 FL
36	1		*TANK, WINDSHIELD WASHER	Crumpled	75.00 FL	*75.00 FL
37	1		*MOTOR, WINDSHIELD WASHER	Broken	30.00 FL	*30.00 FL
38	1		*GASKET, W/SHLD WASHER MOTOR	Necessary	4.00 FL	*4.00 FL
39	1		*CAP, WASHER TANK FILLER	Not Necessary	7.00 FL	*- FL
40	1		*HEADLAMP ASSY, LH	Broken	663.00 FL	*663.00 FL
41	1		*HEADLAMP ASSY, RH	Missing	663.00 FL	*663.00 FL
42	1		*GRILLE, RADIATOR	Not Necessary	554.00 FL	*- FL
43	1		*BRACKET, FR BUMPER, LH	Not Necessary	13.00 FL	*- FL
44	1		*BRACKET, FR BUMPER, RH	Missing	13.00 FL	*13.00 FL
45	1		*COVER, HEADLAMP SUPT PANEL	Crumpled	62.00 FL	*62.00 FL
46	1		*GRILLE, FR UNDER	Not Necessary	165.00 FL	*- FL
47	1		*FACE, FR BUMPER	Broken	706.00 FL	*706.00 FL
48	1		*MARK, THREE-DIA	Necessary	70.00 FL	*70.00 FL
49	1		*GARNISH, FR BUMPER, RH	Cut	127.00 FL	*127.00 FL
50	1		*COVER, FR BUMPER	Not Necessary	12.00 FL	*- FL
51	10		*CLIP, FR BUMPER	Necessary	40.00 FL	*40.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*HOOD	Dented	737.00 FL	*737.00 FL
53	1		*HINGE, HOOD, LH	Not Necessary	56.00 FL	*- FL
54	1		*HINGE, HOOD, RH	Not Necessary	56.00 FL	*- FL
55	5		*CLIP, HOOD INSULATOR	Necessary	15.00 FL	*15.00 FL
56	1		*LATCH, HOOD	Not Necessary	69.00 FL	*- FL
57	1		*ROD, HOOD SUPPORT	Bent	37.00 FL	*37.00 FL
58	1		*INSULATOR, HOOD	Not Necessary	177.00 FL	*- FL
59	1		*LINK KIT, F/SUSP STABILIZER (Supplementary)	Bent	28.00 FL	*28.00 FL
60	1		*STOPPER, FR SUSP STRUT (Supplementary)	Necessary	27.00 FL	*27.00 FL
61	1		*GARNISH, FR PILLAR, RH (Supplementary)	Broken	30.00 FL	*30.00 FL
62	10		*CLIP, RR BUMPER (Supplementary)	Necessary	30.00 FL	*30.00 FL
63	1		*GROMMET, HOOD LOCKING (Supplementary)	Broken	4.00 FL	*4.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,002.00	8,408.00
- List Item Discount on L Items 23.00/23.00% (\$)	3,287.16	1,923.03
Total Parts (\$)	12,714.84	6,484.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER FACE, RH FRONT FENDER. REPLACE FRONT BODY KITS, RH SIDE SKIRTING. REPAIR RH FRONT DOOR, REPAIR RH SIDE PANEL	New	2,250.00	1,800.00
2	REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK	New	100.00	0.00
3	TOP UP AIR CON GAS AND CHECK A/CON SYSTEM	New	80.00	0.00
4	REMOVE AND REPLACE FRONT BODY KITS AND RH SIDE SKIRTING	New	160.00	160.00
5	PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, FRONT BODY KITS, RH FRONT FENDER, RH FRONT DOOR, RH SIDE SKIRTING, RH SIDE SILL PANEL AND AFFECTED PORTION	New	3,150.00	2,450.00
6	APPLY BODY SEALANT	New	160.00	40.00
7	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	PERFORM RUST PREVENTION	New	80.00	0.00
9	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
10	LABOUR RENEW RH SPORT RIM INCLUDING BALANCING	New	30.00	30.00
11	RENEW FRT U/CARRIAGE DAMAGES	New	675.00	400.00
12	SUPPLY RH FRONT TIRE	New	300.00	300.00
13	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST (Supplementary)	New	120.00	120.00
Gross Labour Cost (\$\$)			7,255.00	5,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >