

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21001082/AEA3Q2**Date:** 17/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900166352
Claimant Vehicle No :	SJE5731X	Insured Vehicle No :	SKL522S
Date of Loss:	21/01/2021	Nature of Claim:	TP
		Claim No:	2216694743SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE5731X	Engine No:	3ZZ4746356
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106103124
Reg. Date:	29/04/2008 (Man. Year: 2008)	Odometer:	267818 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,326.85	6,854.37	13,472.48	66.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,980.00	3,140.00	4,840.00	60.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,306.85	9,994.37	18,312.48	64.69
Approved Total (Overridden) (S\$)		8,000.00		
Nett Amount (S\$)	28,306.85	8,000.00	20,306.85	71.74
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
		(S\$)		
		8,540.00		
Liabe Amount (50.00%) (S\$)		4,270.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,272.00		
Global Sum Settlement (S\$)		4,270.00		

INSPECTION

Date of Assignment: 22/01/2021

Date Inspected: 22/01/2021 Inspected At:

Estimated Period of Repair: 8.0 days

Cn Motors Pte Ltd (HQ)
1 KAKI BUKIT AVENUE 6 BLK C #01-41
AUTOBAY @ KAKI BUKIT
Singapore 417883

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	561.85 F	*- FL
2	8		*FRONT BUMPER CLIP	Not Necessary	52.00 F	*- FL
3	1		*FRONT R/H BUMPER SIDE RETAINER	Not Necessary	122.10 F	*- FL
4	1		*FRONT R/H FENDER	Dented	374.10 F	*374.10 FL
5	1		*FRONT R/H FENDER VVTI LOGO	Necessary	47.60 F	*47.60 FL
6	1		*FRONT R/H FENDER COWLING	Deformed	182.10 F	*182.10 FL
7	6		*FRONT R/H FENDER COWLING CLIP	Necessary	39.00 F	*39.00 FL
8	1		*FRONT R/H DOOR	Dented	1,135.30 F	*1,135.30 FL
9	2		*FRONT R/H DOOR HINGE	Not Necessary	364.80 F	*- FL
10	2		*FRONT R/H DOOR FRAME STICKER	Necessary	264.50 FS	*60.00 FS
11	1		*FRONT R/H DOOR PROTECTOR	Cut	220.40 F	*110.00 FL
12	1		*FRONT R/H DOOR OUTER HANDLE	Not Necessary	123.20 F	*- FL
13	1		*FRONT R/H DOOR OUTER HANDLE COVER	Not Necessary	43.10 F	*- FL
14	1		*FRONT R/H DOOR SIDE MIRROR ASSY	Not Necessary	959.80 F	*- FL
15	1		*FRONT R/H RIM	Cut	680.00 FS	*400.00 FS
16	1		*FRONT R/H TYRE	Not Necessary	350.00 F	*- FL
17	1		*FRONT R/H LOWER ARM	Bent	581.90 F	*298.00 FL
18	1		*FRONT R/H KNUCKLE ARM	Damaged	561.60 F	*561.60 FL
19	1		*FRONT R/H KNUCKLE ARM BEARING	Necessary	191.80 F	*191.80 FL
20	1		*FRONT R/H SHOCK ABSORBER	Bent	381.90 F	*381.90 FL
21	1		*FRONT R/H DRIVE SHAFT	Not Necessary	1,712.40 F	*- FL
22	1		*FRONT STEERING RACK	Bent	1,822.50 F	*1,822.50 FL
23	1		*L/H ROCKER PANEL SKIRT	Deformed	688.00 F	*388.00 FL
24	10		*L/H ROCKER PANEL SKIRT CLIP	Necessary	65.00 F	*30.00 FL
25	1		*R/H ROCKER PANEL	Repair	788.00 F	*- FL
26	1		*REAR BUMPER	Torn	476.20 F	*476.20 FL
27	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
28	1		*REAR R/H BUMPER SIDE RETAINER	Necessary	122.10 F	*32.00 FL
29	1		*REAR R/H DOOR	Dented	1,135.30 F	*1,135.30 FL
30	2		*REAR R/H DOOR FRAME STICKER	Necessary	264.50 FS	*60.00 FS
31	1		*REAR R/H DOOR PROTECTOR	Cut	171.40 F	*115.00 FL
32	1		*REAR R/H FENDER	Repair	792.50 F	*- FL
33	1		*REAR R/H FENDER COWLING	Not Necessary	182.10 F	*- FL
34	6		*REAR R/H FENDER COWLING CLIP	Not Necessary	39.00 F	*- FL
35	1		*REAR R/H TAIL LAMP	Not Necessary	342.90 F	*- FL
36	1		*REAR R/H RIM	Cut	680.00 FS	*400.00 FS
37	1		*REAR R/H TYRE	Not Necessary	350.00 F	*- FL
38	1		*REAR R/H SHOCK ABSORBER	Not Necessary	381.90 F	*- FL
39	1		*REAR R/H AXLE BEARING	Damaged	562.10 F	*562.10 FL
40	1		*REAR AXLE	Not Necessary	2,355.60 F	*- FL
41	1		*REAR WINDSCREEN MOULDING	Not Necessary	106.30 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,326.85	8,832.50
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,978.13
Total Parts (\$)	20,326.85	6,854.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT & REAR UNDERCARRIAGE	New	550.00	400.00
2	TO REMOVE & REFIT DRIVE SHAFT & STEERING RACK	New	480.00	120.00
3	TO REMOVE & REFIT FRONT & REAR L/H DOOR ,GEAR MOTOR ,LOCK,RUBBER ,GLASS & TRIM BOARD	New	380.00	160.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	0.00
6	GUM	New	50.00	0.00
7	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
8	TO CHECK WIRING	New	100.00	30.00
9	TUFF KOTE	New	150.00	100.00
10	TOWING FEE	New	1,500.00	0.00
11	PANEL BEATING	New	2,400.00	1,000.00
12	SPRAY PAINTING	New	2,000.00	1,200.00
Gross Labour Cost (\$\$)			7,980.00	3,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >