

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21001085/T1PA3Q2
Date: 10/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800122701
Claimant Vehicle No :	SHC65C	Insured Vehicle No :	SMF1156S
Date of Loss:	21/01/2021	Nature of Claim:	TP
		Claim No:	3281822965SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC65C	Engine No:	2ZRS044754
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FUX03557530
Reg. Date:	31/05/2017 (Man. Year: 2017)	Odometer:	353805 km
Colour:	Yellow		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,430.77	1,126.02	304.75	21.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	630.00	450.00	41.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,510.77	1,756.02	754.75	30.06
Approved Total (Overridden) (S\$)		1,400.00		

(S\$)	2,510.77	1,400.00	1,110.77	44.24
+ GST 7.00/7.00% (S\$)	175.75	98.00	77.75	44.24
Nett Amount (S\$)	2,686.52	1,498.00	1,188.52	44.24
+ Loss of Use (3.5 x S\$50.00/day) (S\$)		175.00		
+ Car Rental (3.5 x S\$125.40/day) (S\$)		438.90		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,113.90		
Global Sum Settlement (S\$)		2,100.00		

INSPECTION

Date of Assignment: 22/01/2021

Date Inspected: 22/01/2021

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	458.60 FL	*458.60 FL
2	1		*REAR BUMPER UNDER COVER	Deformed	552.60 FL	*552.60 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	318.80 FL	*318.80 FL
4	10		*BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
5	2		*REAR BUMPE SIDE RETAINER LH/RH	Not Necessary	225.40 FL	*- FL
6	1		*TOWING COVER	Deformed	82.70 FL	*82.70 FL
7	1		*REVERSE SENSOR	Not Necessary	135.70 FS	*- FS
8	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,845.80	1,484.70
- List Item Discount on L Items 25.00/25.00% (\$)	415.03	358.68
Total Parts (\$)	1,430.77	1,126.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	WIRING	New	60.00	0.00
4	TUFF KOTE	New	60.00	0.00
5	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
Gross Labour Cost (S\$)			1,080.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >