



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 5121A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	CRACKED	507.40	507.40
1	FRONT BUMPER LH TOW COVER (CONSISTENT)	SERVICEABLE	32.00	-
1	FRONT BUMPER LH SIDE RETAINER (CONSISTENT)	SERVICEABLE	191.30	-
1	FRONT BUMPER INNER REINFORCEMENT (CONSISTENT)	BENT	379.20	379.20
1	SET FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	40.00	40.00
1	LH HEADLAMP (CONSISTENT)	MTG CRACKED	748.10	748.10
1	FRONT GRILLE ASSY (CONSISTENT)	MTG CRACKED	580.80	490.90
1	FRONT BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	756.60	-
1	FRONT BONNET CENTRE 'TOYOTA' LOGO (CONSISTENT)	NOT NECESSARY	66.10	-
	LESS 25% DISCOUNT		-825.38	-541.40
			2,476.12	1,624.20
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	BENT	45.00	25.00
			45.00	25.00
	<u>LABOUR</u>			
	LABOUR CHARGES FOR REMOVE /REFIT,CUTTING /WELDING AND REPLACEMENT OF DAMAGES.INCLUSIVE OF THE REPAIR OF FRONT BONNET.		600.00	350.00
	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES.		800.00	400.00
	TO CHECK WIRING & LIGHTINGS.		40.00	20.00
	TO SUPPLY AND APPLY ANTI RUST TREATMENT.	NOT NECESSARY	50.00	-
			1,490.00	770.00
	GRAND TOTAL		4,011.12	2,419.20



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00
---	--	--	-----------------

Report Ref No. CC4/ASM21001089/Kba3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.