

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD	_	Ref:	CC4/ASM21001089/Kba3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	07/06/2021	
	ATTN:LYNN			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKG 8380H	Veh. Inspected		GBJ 5121A	
	Policy No.	VPA/P1745355	Coverage (\$)		0.00	
	Claim No.	S0M02ZHE	Excess (\$)		0.00	
	Assign From		Assign Date		26/01/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HIACE (M)	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTFHT02PX00249062	Colour		WHITE	
	Odometer	88197 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15X8	BRIDGESTONE		3 mm	
	L/H Front Tyre	195 R15X8	BRIDGESTONE		3 mm	
	R/H Rear Tyre	195 R15X8	BRIDGESTONE		4 mm	
	L/H Rear Tyre	195 R15X8	BRIDGESTONE		4 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	23/12/2020	Inspection Date	е	26/01/2021	
	Survey held at	GUAN MOTOR WORKS				
		176 SIN MING DRIVE				
		#02-03 SIN MING AUTOCARE SINGAPORE 575721				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					