

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:**

CC4/III21001093/KGS3Q2

**Date:**

17/12/2021

**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D18MCV0001290\_02

**Claimant Vehicle No :** SHB9833Z**Insured Vehicle No :**

GBA8235H

Date of Loss: 22/01/2021

Nature of Claim:

TP

Claim No:

MCV2021D0000476

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SHB9833Z**

Make &amp; Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZR2H04736

Reg. Date: 23/10/2020 (Man. Year: 2020)

Chassis No: JTDKB3FU003092305

Colour: Metallic Pearl White/Red

Odometer: 0 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 7 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 7 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,449.80	3,843.17	7,606.63	66.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	1,270.00	3,110.00	71.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>15,829.80</b>	<b>5,113.17</b>	<b>10,716.63</b>	<b>67.70</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,108.09</b>	<b>357.92</b>	<b>750.17</b>	<b>67.70</b>

<b>Nett Amount (S\$)</b>	<b>16,937.89</b>	<b>5,471.09</b>	<b>11,466.80</b>	<b>67.70</b>
<hr/>				
+ Loss of Use (5.0 x S\$40.00/day) (S\$)		200.00		
+ Car Rental (5.0 x S\$81.13/day) (S\$)		405.65		
+ Doc/Search Fee (S\$)		7.45		
<hr/>				
<b>Nett Liability (S\$)</b>		<b>6,084.19</b>		
<hr/>				

INSPECTION

Date of Assignment: 22/01/2021

Date Inspected: 25/01/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)  
 2, Ang Mo Kio Street 63  
 Singapore 569111

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2021)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB9833Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD SUB-ASSY	Repair	983.10 FL	*- FL
2	1		*LOCK ASSY ,HOOD	Repair	135.00 FL	*- FL
3	1		*HINGE ASSY ,HOOD, LH	Repair	58.90 FL	*- FL
4	1		*HINGE ASSY ,HOOD, RH	Repair	58.90 FL	*- FL
5	1		*COVER SUB-ASSY ,FRONT PILLAR ,UPR RH	Serviceable	100.40 FL	*- FL
6	1		*COVER ,FRONT BUMPER	Cracked	521.00 FL	*521.00 FL
7	1		*ABSORBER ,FRONT BUMPER ENERGY	Serviceable	80.20 FL	*- FL
8	1		*REINFORCEMENT SUB-ASSY ,FRONT BUMPER	Repair	716.60 FL	*- FL
9	1		*COVER ,FRONT BUMPER HOLE ,RH	Serviceable	30.20 FL	*- FL
10	1		*MOULDING ,FRONT BUMPER SIDE ,RH	Dented	95.60 FL	*95.60 FL
11	1		*STAY SUB-ASSY ,FRONT BUMPER ,RH	Repair	47.50 FL	*- FL
12	1		*BRACKET ,FRONT BUMPER SIDE, RH	Distorted	59.30 FL	*59.30 FL
13	1		*SUPPORT ,FRONT BUMPER SIDE RH	Serviceable	80.10 FL	*- FL
14	1		*LINER FRONT FENDER ,RH	Distorted	202.50 FL	*202.50 FL
15	1		*COVER ,RADIATOR SUPPORT OPENING	Serviceable	211.50 FL	*- FL
16	1		*FENDER SUB-ASSY ,FRONT RH	Bent	977.80 FL	*977.80 FL
17	1		*EMBLEM SIDE PANEL RH	Necessary	54.60 FL	*54.60 FL
18	1		*BRACKET ,HEADLAMP ,RH	Serviceable	34.80 FL	*- FL
19	1		*MOTOR ,HEADLAMP LEVELING RH	Serviceable	487.50 FL	*- FL
20	1		*COMPUTER SUB-ASSY ,HEADLAMP RH NO.1	Serviceable	3,772.50 FL	*- FL
21	1		*UNIT ASSY ,HEADLAMP RH	Cracked	2,637.60 FL	*2,637.60 FL
22	1		*GRILLE SUB-ASSY ,RADIATOR	Distorted	422.50 FL	*422.50 FL
23	1		*JAR ASSY ,WINDSHIELD WASHER	Serviceable	219.10 FL	*- FL
24	1		*SET FRONT FENDER CLIP	Necessary	65.00 FS	*65.00 FS
25	1		*SET FRONT FENDER LINER CLIP	Not Necessary	75.00 FS	*- FS
26	1		*SET FRONT BUMPER CLIP	Necessary	90.00 FS	*50.00 FS
27	1		*TYRE	Serviceable	350.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*RIM	Serviceable	1,879.40 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					14,446.60	5,085.90
- List Item Discount on L Items 25.00/25.00% (\$)					2,996.80	1,242.73
Total Parts (\$)					11,449.80	3,843.17

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,600.00	500.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	660.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>4,380.00</b>	<b>1,270.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >