

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21001112/QTF3Q2
Date: 19/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00033562004
Claimant Vehicle No :	SLL2912A	Insured Vehicle No :	WC6432J
Date of Loss:	20/01/2021	Nature of Claim:	TP
		Claim No:	SNM21D200375/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL2912A	Engine No:	P520428973
Make & Model:	MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A)	Chassis No:	JM6BN22A8H0141163
Reg. Date:	20/02/2017 (Man. Year: 2017)	Odometer:	304033 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,424.48	758.40	666.08	46.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,000.00	800.00	44.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,224.48	1,758.40	1,466.08	45.47
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	3,224.48	1,400.00	1,824.48	56.58
+ GST 7.00/7.00% (S\$)	225.71	98.00	127.71	56.58
Nett Amount (S\$)	3,450.19	1,498.00	1,952.19	56.58

INSPECTION

Date of Assignment:	31/01/2021	
Date Inspected:	25/01/2021	Inspected At: Lion City Rentals Pte Ltd (HQ) 60 Jalan Lam Huat, #04-35/36 Carros Centre Singapore 737569
Estimated Period of Repair:	3.0 days	

Adjuster: OI SUN PIN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Mar 2021)

Parts: 143 MAZDA 3 1.4 SEDAN 1.5L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLL2912A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*F/R FENDER	Dented	680.60 FL	*450.00 FL
2	1		*F/R MIRROR COVER	Repair	220.00 FL	*- FL
3	1		*F/R DOOR MIRROR	Crumpled	880.00 FL	*498.00 FL
					Sub Total (\$)	1,780.60
					- List Item Discount on L Items 20.00/20.00% (\$)	356.12
					Total Parts (\$)	1,424.48

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR REMOVING F/R FENDER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	900.00	500.00
2	TO RESPRAY F/R FENDER AND F/R DOOR	New	900.00	500.00
Gross Labour Cost (S\$)			1,800.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >