

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001116/EVF3E2

Date: 10/02/2021

REFERENCE

Insured/Claimant:	NG KIA WHYE ADRIAN	Policy No:	2070164204		
Date of Loss:	22/01/2021	Nature of Claim:	OD	Claim No:	5301238076SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFA1778G		
Make & Model:	KIA STINGER, 2.0 (A)	Engine No:	G4KLLH031295
Reg. Date:	24/11/2020 (Man. Year: 2020)	Chassis No:	KNAE351AML6090665
Colour:	White	Odometer:	1342 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$147,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,736.80	3,831.20	2,905.60	43.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	900.00	750.00	45.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,386.80	4,731.20	3,655.60	43.59
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	8,086.80	4,431.20	3,655.60	45.20
+ GST 7.00/7.00% (S\$)	566.08	310.18	255.90	45.21
Nett Amount (S\$)	8,652.88	4,741.38	3,911.50	45.20

INSPECTION

Date of Assignment:	25/01/2021		
Date Inspected:	25/01/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*LAMP ASSY-HEAD, RH	Broken	3,977.00 FL	*3,977.00 FL
3	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	105.00 FL	*- FL
4	1		*GRILLE-FRONT BUMPER	Not Necessary	391.00 FL	*- FL
5	1		*COVER-FR BUMPER	Dented	646.00 FL	*646.00 FL
6	1		*LIP ASSY-FRONT BUMPER	Not Necessary	22.00 FL	*- FL
7	1		*COVER ASSY-AIR CURTAIN, RH	Broken	126.00 FL	*126.00 FL
8	1		*AIR DUCT-FR BUMPER, RH	Not Necessary	24.00 FL	*- FL
9	1		*BRKT ASSY-FRT BUMPER SIDE MTG	Broken	15.00 FL	*15.00 FL
10	1		*KIA STINGER BODYKIT	Not Necessary	2,442.00 FS	*- FS
					Sub Total (\$)	7,798.00 4,784.00
					- List Item Discount on L Items 20.00/20.00% (\$)	1,061.20 952.80
					Total Parts (\$)	6,736.80 3,831.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRONT BUMPER, FRT RH HEAD LAMP & AFFECTED AREA	New	800.00	400.00
2	PAINT WORK ON FRONT BUMPER PANEL	New	700.00	350.00
3	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (\$\$)			1,650.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >