



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV13459/NG KIA WHYE, ADRIAN(WU JIAWEI)
	Reg No/Reg Date	SFA1778G / 24/11/202
	Date In/Mileage	25/01/2021/ 0
	Chassis No	KNAE351AML6090665
	Engine No	G4KLLH031295
	Make/Model	KIA/STINGER 2.0 A GAA3 RED LEATHER
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
LAX00000	Credit	23/01/2021/ 09:43	QUK	282 / Kevin Leong	27889				
Description of Goods / Services						Qty	Unit Price	Disc%	Amount
E PNT88000									800.00
REPLACE FRONT BUMPER, FRT RH HEAD LAMP & AFFECTED AREA									
E PNT98000									700.00
PAINT WORK ON FRONT BUMPER PANEL									
A 54900099									30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM									
A 10028901									120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST									
USING HI-SCAN PRO TEST									
M SUNDRY									50.00
SUNDRIES									
M LAMP ASSY-HEAD,RH						1.00	3977.00	20.00	3181.60
M ABSORBER-FRONT BUMPER ENERGY						1.00	105.00	20.00	84.00
M GRILLE-FRONT BUMPER						1.00	391.00	20.00	312.80
M COVER-FR BUMPER						1.00	646.00	20.00	516.80
M LIP ASSY-FRONT BUMPER						1.00	22.00	20.00	17.60
M COVER ASSY-AIR CURTAIN,RH						1.00	126.00	20.00	100.80
M AIR DUCT-FR BUMPER,RH						1.00	24.00	20.00	19.20
M BRKT ASSY-FRT BUMPER SIDE MTG,						1.00	15.00	20.00	12.00
M KIA STINGER BODYKIT						1.00	2442.00	00.00	2442.00

Confirm & accepted by

	Nett	8,386.80
7% GST on	8386.80	587.08
Total Payable		8,973.88

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.