

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001121/ETD3E2

Date: 08/03/2021

REFERENCE

Insured/Claimant:	KAMARUL ZAMAN BIN RAMLI	Policy No:	1800035674-01	
Date of Loss:	22/01/2021	Nature of Claim:	OD	Claim No: 7296733314SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX7631P	Engine No:	4J11XK6129
Make & Model:	MITSUBISHI OUTLANDER, 2.0 CVT SUNROOF (A)	Chassis No:	GF7W0401070
Reg. Date:	11/04/2018 (Man. Year: 2017)	Odometer:	74210 km
Colour:	Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 4 mm	Rear Left Side:	Toyo 4 mm
Front Right Side:	Toyo 4 mm	Rear Right Side:	Toyo 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,938.05	6,044.62	1,893.43	23.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,210.00	2,760.00	1,450.00	34.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,148.05	8,804.62	3,343.43	27.52
+ GST 7.00/7.00% (S\$)	850.36	616.32	234.04	27.52
Nett Amount (S\$)	12,998.41	9,420.94	3,577.47	27.52

INSPECTION

Date of Assignment: 25/01/2021

Date Inspected: 25/01/2021 Inspected At:

Estimated Period of Repair: 6.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*FRT BUMPER	Broken	1,048.00 FL	*859.00 FL
3	1		*EXTENSION, FR BUMPER	Not Necessary	426.00 FL	*- FL
4	1		*GARNISH, FR BUMPER, LH	Cut	75.00 FL	*75.00 FL
5	1		*BRACKET, FR BUMPER SIDE, LH	Broken	18.00 FL	*18.00 FL
6	1		*GARNISH, FR BUMPER SIDE	Broken	48.00 FL	*48.00 FL
7	1		*GARNISH, FR BUMPER SIDE	Broken	220.00 FL	*220.00 FL
8	1		*GARNISH, FR BUMPER SIDE	Broken	112.00 FL	*112.00 FL
9	1		*COVER, FR BUMPER	Not Necessary	294.00 FL	*- FL
10	1		*REINFORCEMENT, FR BUMPER	Not Necessary	503.00 FL	*- FL
11	1		*BAR, FR BUMPER GUARD	Not Necessary	130.00 FL	*- FL
12	1		*GRILLE ASSY, RADIATOR	Not Necessary	569.00 FL	*- FL
13	1		*FENDER, FR LH	Dented	688.00 FL	*688.00 FL
14	1		*SHIELD, FR WHEELHOUSE, LH	Crushed	164.00 FL	*164.00 FL
15	1		*MOULDING, FR BUMPER, LH	Cut	116.00 FL	*116.00 FL
16	1		*MOULDING, FR WHEEL ARCH, LH	Cut	199.00 FL	*199.00 FL
17	1		*HEADLAMP ASSY, LH	Broken	2,125.00 FL	*2,125.00 FL
18	1		*LAMP ASSY, FOG, FR LH	Not Necessary	348.00 FL	*- FL
19	1		*AERO KIT - OUTLANDER	Broken	1,554.00 FS	*1,554.00 FS
20	1		*WHEEL, SPARE TIRE DISC LHF	Cut	1,102.00 FL	*1,102.00 FL
21	1		*CLIP, ENG ROOM COVER (X10) (Supplementary)	Necessary	20.00 FL	*20.00 FL
22	1		*CLIPS (X10) (Supplementary)	Necessary	30.00 FL	*30.00 FL
23	1		*RIVET, FR BUMPER (X6) (Supplementary)	Necessary	30.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,839.00	7,380.00
- List Item Discount on L Items 23.00/23.00% (S\$)	1,900.95	1,335.38
Total Parts (S\$)	7,938.05	6,044.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT BUMPER BODY KIT & LHF FENDER. REPAIR LHF DOOR	New	2,250.00	900.00
2	RESPRAY FRT BUMPER, FRT BUMPER BODY KIT, LHF FENDER & LHF DOOR	New	1,400.00	1,400.00
3	RENEW LHF SPORT RIM & TRANSFER TYRE	New	30.00	30.00
4	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	0.00
8	APPLY ZERTONA CORROSION ON AFFECTED AREAS	New	180.00	160.00
Gross Labour Cost (\$\$)			4,210.00	2,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >