

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV16223/Kamarul Zaman Bin Ramli Reg No/Reg Date SLX7631P / 11/04/201 Date In/Mileage / 0 Chassis No GF7W0401070 Engine No 4J11XK6129 Make/Model MIT/OUTLANDER 2.0 2WD CVT SPORTS (9 Colour/Trim PO2 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	22/01/2021/ 17:37	BLE	261 / Edwin Caina	62199			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000					450 X 2			2250.00
RENEW FRT BUMPER , FRT BUMPER BODY KIT & LHF FENDER								1400.00
REPAIR LHF DOOR								30.00
E PNT98000					350 X 4			30.00
RESPRAY FRT BUMPER , FRT BUMPER BODY KIT , LHF FENDER & LHF DOOR								30.00
M SUNDRY								120.00
RENEW LHF SPORT RIM & TRANSFER TYRE								120.00
A 54900099								80.00
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								180.00
A 10028901								20.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
A WHEELALIGNMENTBP								
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								
APPLY ZERTONA PAINT PROTECTION ON AFFECTED AREAS								
M SUNDRY								
Sundries					1.00	859	23.00	806.96
M FRT BUMPER	BR				1.00	426.00	23.00	328.02
M EXTENSION,FR BUMPER	? X N/A				1.00	75.00	23.00	57.75
M GARNISH,FR BUMPER,LH	CHT (fog lamp)				1.00	18.00	23.00	13.86
M BRACKET,FR BUMPER SIDE,LH	BR				1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER SIDE	BR (chrome)				1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE	BR (chrome)				1.00	112.00	23.00	86.24
M GARNISH,FR BUMPER SIDE	BR (chrome)				1.00	294.00	23.00	226.38
M COVER,FR BUMPER	? X N/A				1.00	503.00	23.00	387.31
M REINFORCEMENT,FR BUMPER	X N/A				1.00	130.00	23.00	100.10
M BAR,FR BUMPER GUARD	X N/A				1.00	569.00	23.00	438.13
M GRILLE ASSY,RADIATOR	? X N/A				1.00	688.00	23.00	529.76
M FENDER,FR LH	00				1.00	164.00	23.00	126.28
M SHIELD,FR WHEELHOUSE,LH	9 - CR4							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV16223/Kamarul Zaman Bin Ramli Reg No/Reg Date SLX7631P / 11/04/201 Date In/Mileage / 0 Chassis No GF7W0401070 Engine No 4J11XK6129 Make/Model MIT/OUTLANDER 2.0 2WD CVT SPORTS (9 Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	22/01/2021/ 17:37	BLE	261 / Edwin Caina	62199			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	MOULDING,FR BUMPER,LH	CUT			1.00	116.00	23.00	89.32
M	MOULDING,FR WHEEL ARCH,LH	CUT			1.00	199.00	23.00	153.23
M	HEADLAMP ASSY,LH	OR			1.00	2125.00	23.00	1636.25
M	LAMP ASSY,FOG,FR LH	X NM			1.00	348.00	23.00	267.96
M	AERO KIT - OUTLANDER	OR			1.00	1554.00	00.00	1554.00
M	WHEEL,SPARE TIRE DISC LHF	CUT			1.00	1102.00	23.00	848.54

Estimate

SURVEYOR NAME: Steve CLKK) 25/1/21, 10.30 amSURVEYOR SIGNATURE: OO- NM AutLDATE: EXPRESS - ?REMARKS: P/PMy BL sy6 daysLKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey

Confirm & accepted by are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

7% GST on 12086.45 12,086.45
846.05
Total Payable 12,932.50

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.