

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001124/ETF3E2
Date: 15/02/2021

REFERENCE

Insured/Claimant: TONG NGIAP SHIEK ALEC Policy No: 1800085913
Date of Loss: 21/01/2021 Nature of Claim: OD Claim No: 8417709519SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ5652D**
Make & Model: MITSUBISHI LANCER, 1.3 (A) Engine No: 4A92CP2588
Reg. Date: 14/07/2017 (Man. Year: 2017) Chassis No: JMYSRCY1AGU006675
Colour: White Odometer: 26927 km
Engine Capacity: 1590 cc
Market Value/New Car Price: S\$53,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,594.90	5,065.76	4,529.14	47.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,070.00	4,270.00	800.00	15.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,664.90	9,335.76	5,329.14	36.34
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	14,364.90	9,035.76	5,329.14	37.10
+ GST 7.00/7.00% (S\$)	1,005.54	632.50	373.04	37.10
Nett Amount (S\$)	15,370.44	9,668.26	5,702.18	37.10

INSPECTION

Date of Assignment: 25/01/2021
Date Inspected: 25/01/2021 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Broken	50.00 FS	*50.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*FACE, FR BUMPER	Dented	1,040.00 FL	*1,040.00 FL
4	1		*GARNISH, FR BUMPER, RH	Not Necessary	37.00 FL	*- FL
5	1		*GARNISH, FR BUMPER, LH	Not Necessary	37.00 FL	*- FL
6	1		*GRILLE, FR BUMPER	Broken	78.00 FL	*78.00 FL
7	1		*SUPPORT, FR BUMPER, RH	Broken	13.00 FL	*13.00 FL
8	1		*SUPPORT, FR BUMPER, LH	Broken	13.00 FL	*13.00 FL
9	1		*COVER, HEADLAMP SUPT PANEL	Cut	70.00 FL	*70.00 FL
10	1		*BRACKET, FR BUMPER SIDE, RH	Not Necessary	17.00 FL	*- FL
11	1		*BRACKET, FR BUMPER SIDE, LH	Not Necessary	17.00 FL	*- FL
12	1		*REINFORCEMENT, FR BUMPER	Bent	93.00 FL	*93.00 FL
13	1		*COVER, FR BUMPER GRILLE	Missing	5.00 FL	*5.00 FL
14	1		*COVER, FR BUMPER GRILLE	Missing	5.00 FL	*5.00 FL
15	1		*COVER, ENG ROOM UNDER, FR	Not Necessary	173.00 FL	*- FL
16	1		*COVER, ENG ROOM SIDE, RH	Not Necessary	88.00 FL	*- FL
17	1		*COVER, ENG ROOM SIDE, LH	Not Necessary	87.00 FL	*- FL
18	1		*HOOD	Bent	913.00 FL	*913.00 FL
19	1		*LATCH, HOOD	Bent	58.00 FL	*58.00 FL
20	1		*BRACKET, FR FENDER, RH	Not Necessary	16.00 FL	*- FL
21	1		*BRACKET, FR FENDER, LH	Not Necessary	16.00 FL	*- FL
22	1		*FENDER, FR LH	Repair	688.00 FL	*- FL
23	1		*PANEL, HEADLAMP SUPPORT, UPR	Bent	296.00 FL	*296.00 FL
24	1		*PNL, HEADLAMP SUPT, UPR RH	Not Necessary	86.00 FL	*- FL
25	1		*PNL, HEADLAMP SUPT, UPR LH	Not Necessary	86.00 FL	*- FL
26	1		*HEADLAMP ASSY, LH	Broken	846.00 FL	*846.00 FL
27	1		*HEADLAMP ASSY, RH	Not Necessary	846.00 FL	*- FL
28	1		*LAMP ASSY, FOG, FR RH	Not Necessary	303.00 FL	*- FL
29	1		*LAMP ASSY, FOG, FR LH	Not Necessary	303.00 FL	*- FL
30	1		*LAMP ASSY, SIDE MARKER, LH	Not Necessary	607.00 FL	*- FL
31	1		*LAMP ASSY, SIDE MARKER, RH	Not Necessary	607.00 FL	*- FL
32	1		*CONDENSER ASSY, A/C REFRIGE	Bent	1,134.00 FL	*1,134.00 FL
33	1		*HOSE, A/C COMPR DISCHARGE	Not Necessary	197.00 FL	*- FL
34	1		*HOSE, A/C COMPR SUCTION	Not Necessary	263.00 FL	*- FL
35	1		*PIPE, A/C CONDENSER OUTLET	Not Necessary	115.00 FL	*- FL
36	1		*PIPE, RR A/C DISCHARGE	Not Necessary	132.00 FL	*- FL
37	1		*RADIATOR ASSY	Bent	1,124.00 FL	*1,124.00 FL
38	1		*TANK ASSY, RADIATOR COND	Not Necessary	60.00 FL	*- FL
39	1		*SHROUD, COOLING FAN	Not Necessary	257.00 FL	*- FL
40	1		*SHROUD, COOLING FAN	Not Necessary	257.00 FL	*- FL
41	1		*MOTOR, COOLING FAN (*)	Not Necessary	467.00 FL	*- FL
42	1		*CAP ASSY, RADIATOR	Not Necessary	94.00 FL	*- FL
43	1		*LLC 4L	Not Necessary	26.00 FL	*- FL
44	1		*GRILLE, RADIATOR (Supplementary)	Broken	268.00 FL	*268.00 FL
45	1		*GROMMET, HEADLAMP (Supplementary)	Necessary	3.00 FL	*3.00 FL
46	1		*REINFORCEMENT, FR BUMPER (Supplementary)	Dented	529.00 FL	*529.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,440.00	6,558.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	2,845.10	1,492.24

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	9,594.90	5,065.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FENDER LH. REPAIR FRT FENDER RH, FRT DOOR LH	New	2,250.00	1,800.00
2	REMOVE & INSTALL AIRCON CONDENSOR	New	100.00	100.00
3	TOP UP AIRCON GAS	New	80.00	80.00
4	SPRAY PAINT FOR FRT BUMPER, BONNET, FRT SUPPORT, FRT FENDER RH & LH, FRT DOOR LH	New	2,450.00	2,100.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
			Gross Labour Cost (S\$)	4,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >