

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001125/ETD3E2

Date: 23/02/2021

REFERENCE

Insured/Claimant:	TEO JIE WEI	Policy No:	1900129578	Claim No:	0731559848SG
Date of Loss:	22/01/2021	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA1721Z	Engine No:	G4FGKH741971
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5047578
Reg. Date:	01/08/2019 (Man. Year: 2018)	Odometer:	6931 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$77,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,598.00	782.40	815.60	51.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	1,960.00	1,280.00	39.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,838.00	2,742.40	2,095.60	43.32
+ GST 7.00/7.00% (S\$)	338.66	191.97	146.69	43.31
Nett Amount (S\$)	5,176.66	2,934.37	2,242.29	43.32

INSPECTION

Date of Assignment:	25/01/2021		
Date Inspected:	25/01/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*COVER-RR BUMPER	Repair	651.00 FL	*- FL
3	1		*COVER-RR BUMPER LWR	Not Necessary	241.00 FL	*- FL
4	1		*BRACKET-RR BEAM UPR MTG, LH	Not Necessary	9.00 FL	*- FL
5	1		*BRACKET-RR BEAM LWR, CTR	Not Necessary	6.00 FL	*- FL
6	1		*GUARD-REAR WHEEL, LH	Not Necessary	75.00 FL	*- FL
7	1		*FILM-ANTI CHIPPG LH	Necessary	27.00 FL	*27.00 FL
8	1		*WHEEL ASSY-ALUMINIUM	Cut	926.00 FL	*926.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,985.00	973.00
- List Item Discount on L Items 20.00/20.00% (S\$)	387.00	190.60
Total Parts (S\$)	1,598.00	782.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER & AFFECTED AREA. REPAIR ON REAR LH FENDER	New	1,920.00	800.00
2	PAINT WORK ON REAR BUMPER & REAR LH FENDER	New	700.00	700.00
3	PERFORM RUST PREVENTION	New	40.00	40.00
4	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	TO APPLY PAINT PROTECTION ON AFFECTED PANEL	New	160.00	0.00
7	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	120.00
8	CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT (Supplementary)	New	120.00	120.00
9	REPALCE RH REAR SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING (Supplementary)	New	30.00	30.00
Gross Labour Cost (\$\$)			3,240.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >