



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/TEO JIE WEI (ZHANG JIEWEI)
	Reg No/Reg Date	SLA1721Z / 01/08/201
	Date In/Mileage	23/01/2021/ 0
	Chassis No	KNAF3416MK5047578
	Engine No	G4FGKH741971
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	23/01/2021/ 11:12	QUK	282 / Kevin Leong	27919

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER & AFFECTED AREA REPAIR ON REAR LH FENDER				1920.00
E PNT98000 PAINT WORK ON REAR BUMPER & REAR LH FENDER				700.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST				120.00
M SUNDRY PERFORM RUST PREVENTION				40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY SUNDRIES				50.00
M SUNDRY TO APPLY PAINT PROTECTION ON AFFECTED PANEL				160.00
M COVER-RR BUMPER	1.00	651.00	20.00	520.80
P COVER-RR BUMPER LWR	1.00	241.00	20.00	192.80
M BRACKET-RR BEAM UPR MTG,LH	1.00	9.00	20.00	7.20
M BRACKET-RR BEAM LWR,CTR	1.00	6.00	20.00	4.80
M GUARD-REAR WHEEL,LH	1.00	75.00	20.00	60.00
M FILM-ANTI CHIPPG LH	1.00	27.00	20.00	21.60

Confirm & accepted by

Nett 3,947.20
7% GST on 3947.20 276.30
Total Payable 4,223.50

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.