



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 6825P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET	NOT NECESSARY	3,082.40	-
1	BONNET INNER TRIM	NOT NECESSARY	408.20	-
1	FRONT FENDER RH	DENTED	2,070.00	894.90
1	FRONT FENDER INNER SHIELD RH	SERVICEABLE	295.00	-
1	HEAD LAMP RH	SCRATCHED	3,890.00	2,236.00
1	HEAD LAMP PANEL RH	NOT NECESSARY	1,283.00	-
1	HEAD LAMP LOWER BRACKET RH	NOT NECESSARY	305.80	-
1	FRONT RIM	NOT NECESSARY	2,480.00	-
1	FRONT WHEEL BEARING RH	NOT NECESSARY	405.00	-
1	FRONT WHEEL BEARING HUB RH	NOT NECESSARY	498.00	-
1	FRONT ABSORBER RH	NOT NECESSARY	782.00	-
1	FRONT KNUCKLE RH	NOT NECESSARY	1,084.00	-
1	FRONT LOWER ARM RH	NOT NECESSARY	692.30	-
1	FRONT UPPER ARM RH	NOT NECESSARY	603.90	-
1	FRONT THRUST ARM RH	NOT NECESSARY	599.10	-
1	FRONT TIE ROD RH	NOT NECESSARY	301.50	-
1	FRONT TIE ROD END RH	NOT NECESSARY	398.70	-
1	FRONT BUMPER	CUT / DISTORTED	2,980.00	1,345.00
2	FRONT BUMPER SIDE RETAINER LH/RH @\$201.80	SERVICEABLE	403.60	-
4	FRONT BUMPER SENSOR @\$365.00	NOT FITTED	1,460.00	-
4	FRONT BUMPER SENSOR HOLDER @\$20.00	NOT FITTED	80.00	-
4	FRONT BUMPER SENSOR O-RING @\$10.00	NOT FITTED	40.00	-
1	FRONT BUMPER SENSOR WIRE HARNESS	NOT FITTED	1,982.00	-
	LESS 10% DISCOUNT		-	-447.59
			26,124.50	4,028.31
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	100.00	-
1	FRONT FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	50.00	-
1	TYRE (SN)	NOT NECESSARY	600.00	-
			750.00	-

Report Ref No. CS/UOI21001129/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS.		1,600.00	600.00
	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS.		1,600.00	500.00
	TO TUFF COAT DAMAGED AREAS.		300.00	30.00
	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS.		200.00	30.00
	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS.		300.00	150.00
	TO RNR FRONT BUMPER SENSOR TO FACILITATE REPAIRS.	NOT NECESSARY	120.00	-
	TO RNR FRONT UNDERCARRIAGE SYSTEM TO FACILITATE REPAIRS.	NOT NECESSARY	400.00	-
	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			4,640.00	1,310.00
	GRAND TOTAL		31,514.50	5,338.31
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,250.00

Report Ref No. CS/UOI21001129/Dqd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.