

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21001130/DQF3Q2

Date: 22/03/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMS/20-419748-CA

Claimant Vehicle No : SLD6636M Insured Vehicle No : FBR8918G

Date of Loss: 02/12/2020 Nature of Claim: TP Claim No: MSC/V/20-000863

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD6636M**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A) Engine No: 1ZR557182

Reg. Date: 24/06/2016 (Man. Year: 2015) Chassis No: MR053REH104546931

Colour: Black Odometer: 233726 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/45R17 Rear Tyre Size: 195/45R17

Front Left Side: Triangle 5 mm Rear Left Side: Triangle 5 mm

Front Right Side: Triangle 5 mm Rear Right Side: Triangle 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,289.89	1,660.34	16,629.55	90.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,890.00	1,410.00	6,480.00	82.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	26,179.89	3,070.34	23,109.55	88.27
+ GST 7.00/7.00% (\$\$)	1,832.59	214.92	1,617.67	88.27
Nett Amount (\$\$)	28,012.48	3,285.26	24,727.22	88.27

INSPECTION

Date of Assignment: 25/01/2021

Date Inspected: 26/01/2021 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/22/2021

Adjuster Report

*NOTE: ACCORDING TO THE REPAIRER, THE CASE HAS BEEN WITHDRAW.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD6636M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER LH	Dented	1,889.58 FL	*981.10 FL
2	1		*REAR FENDER INNER TRIM LH	Not Necessary	634.24 FL	*- FL
3	1		*REAR FENDER INNER SHIELD LH	Not Necessary	210.80 FL	*- FL
4	1		*REAR FENDER FUEL COVER	Not Necessary	293.80 FL	*- FL
5	1		*REAR WINDSCREEN MOULDING	Necessary	296.00 FL	*133.52 FL
6	1		*BOOTLID	Repair	1,455.00 FL	*- FL
7	1		*BOOTLID CHROME MOULDING	Not Necessary	392.10 FL	*- FL
8	1		*BOOTLID TOYOTA LOGO	Serviceable	60.20 FL	*- FL
9	1		*BOOTLID COROLLA EMBLEM	Serviceable	52.60 FL	*- FL
10	1		*BOOTLID ALTIS EMBLEM	Serviceable	62.70 FL	*- FL
11	2		*BOOTLID LAMP LH	Not Necessary	449.10 FL	*- FL
12	1		*BOOTLID WEATHER STRIP	Not Necessary	319.56 FL	*- FL
13	2		*TAIL LAMP LH	Broken	710.98 FL	*412.50 FL
14	2		*TAIL LAMP LOWER BRACKET LH	Not Necessary	122.78 FL	*- FL
15	2		*TAIL LAMP PANEL LH	Not Necessary	492.99 FL	*- FL
16	1		*REAR BUMPER	Dented/Distorted	1,082.00 FL	*580.00 FL
17	2		*REAR BUMPER SIDE RETAINER L+R	Not Necessary	176.00 FL	*- FL
18	2		*REAR BUMPER REFLECTOR LH	Not Necessary	88.82 FL	*- FL
19	1		*REAR REINFORCEMENT BAR	Not Necessary	986.42 FL	*- FL
20	1		*REAR END PANEL	Not Necessary	1,281.20 FL	*- FL
21	1		*REAR END PANEL TOP GARNISH	Not Necessary	229.40 FL	*- FL
22	1		*REAR DOOR LH	Repair	1,782.50 FL	*- FL
23	1		*REAR DOOR WINDOW MOULDING LH	Not Necessary	278.66 FL	*- FL
24	1		*REAR DOOR WEATHER STRIP LH	Not Necessary	410.50 FL	*- FL
25	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	1,520.00 FL	*- FL
26	2		*REAR WHEEL BEARING & HUB ASSY LH	Not Necessary	589.12 FL	*- FL
27	1		*REAR KNUCKLE ARM LH	Not Necessary	710.20 FL	*- FL
28	1		*REAR LOWER ARM LH	Not Necessary	499.80 FL	*- FL
29	1		*REAR ABSORBER LH	Not Necessary	472.80 FL	*- FL
30	1		*REAR AXLE	Not Necessary	2,140.50 FL	*- FL
31	1		*ROCKER PANEL LH	Not Necessary	1,389.50 FL	*- FL
32	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*40.00 FS
33	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
34	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
35	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
36	1		*REAR END PANEL	Not Necessary	80.00 FS	*- FS
37	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*ROCKER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*SPARE WHEEL QUARTER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
41	1		*SPORT RIM	Not Necessary	1,600.00 FS	*- FS
42	1		*TYRE	Not Necessary	300.00 FS	*- FS

Report was unsubmitted during this print-out.

3/22/2021

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					23,559.85	2,187.12
- List Item Discount on L Items 25.00/25.00% (\$)					5,269.96	526.78
Total Parts (\$)					18,289.89	1,660.34
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	400.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,600.00	500.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,600.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	New	200.00	0.00
6	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS	New	250.00	0.00
7	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	0.00
8	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	0.00
9	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
10	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
11	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	New	120.00	40.00
12	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	400.00	120.00
Gross Labour Cost (S\$)			7,890.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >