

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001135/T1GA3Q2
Date: 28/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800142250
Claimant Vehicle No :	SHC562J	Insured Vehicle No :	SLU7742T
Date of Loss:	23/01/2021	Nature of Claim:	TP
		Claim No:	7194443445SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC562J	Engine No:	G4LEJU080637
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVKU107311
Reg. Date:	21/08/2018 (Man. Year: 2018)	Odometer:	398646 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,107.40	983.40	124.00	11.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	1,180.00	500.00	29.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,787.40	2,163.40	624.00	22.39
+ GST 7.00/7.00% (S\$)	195.12	151.44	43.68	22.39

Nett Amount (S\$)	2,982.52	2,314.84	667.68	22.39
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.19/day) (S\$)		375.57		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,842.41		

INSPECTION

Date of Assignment: 25/01/2021

Date Inspected: 25/01/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
2	1		*EMBLEM -IONIQ	Necessary	31.30 FL	*31.30 FL
3	1		*REAR BOOT LOGO CCTPL	Necessary	30.00 FS	*30.00 FS
4	1		*REAR BOOT TEL NUMBER CCTP	Necessary	30.00 FS	*30.00 FS
5	1		*APP LOGO REAR DOOR L/R CC	Necessary	40.00 FS	*40.00 FS
6	1		*COVER -RR BUMPER	Torn	459.40 FL	*459.40 FL
7	1		*MOULDING ASSY -RR BUMPER C	Deformed	451.25 FL	*451.25 FL
8	1		*BRACKET ASSY -RR BUMPER SI	Cracked	55.80 FL	*55.80 FL
9	1		*MOULDING -REAR BUMPER LWR	Repair	155.00 FL	*- FL
10	1		*REFLECTOR /REFLEX ASSY -RR	Cut	41.45 FL	*41.45 FL
11	10		*BUMPER COVER CLIP REAR	Necessary	22.00 FL	*22.00 FL
12	1		*FUEL TANK LID (PETROL ONLY)	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,355.50	1,200.50
- List Item Discount on L Items 20.00/20.00% (\$)	248.10	217.10
Total Parts (\$)	1,107.40	983.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	350.00
2	SPRAYPAINT CHARGE	New	600.00	500.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
4	RENEW ADVERTISEMENT STICKER -BOOT	New	100.00	100.00
5	RENEW ADVERTISEMENT STICKER -FENDER	New	200.00	200.00
Gross Labour Cost (S\$)			1,680.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >