

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001137/T1BA3Q2
Date: 18/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070100658
Claimant Vehicle No :	SHC2501Y	Insured Vehicle No :	SKX9919J
Date of Loss:	24/01/2021	Nature of Claim:	TP
		Claim No:	4922227111SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2501Y	Engine No:	2ZR2F90551
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU303090144
Reg. Date:	13/12/2019 (Man. Year: 2019)	Odometer:	126932 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	474.17	99.25	374.92	79.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	600.00	200.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,274.17	699.25	574.92	45.12
+ GST 7.00/7.00% (S\$)	89.19	48.95	40.24	45.12

Nett Amount (S\$)	1,363.36	748.20	615.16	45.12
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$126.47/day) (S\$)		379.41		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,279.61		
Global Sum Settlement (S\$)		1,250.00		

INSPECTION

Date of Assignment: 25/01/2021

Date Inspected: 25/01/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*COVER FRONT BUMPER	Repair	499.90 FL	*- FL	
2	1		*BRACKET FRT BUMPER EXTENS	Deformed	99.00 FL	*99.00 FL	
3	1		*NO PLATE	Bent	25.00 FS	*25.00 FS	
					Sub Total (\$\$)	623.90	124.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	149.73	24.75
					Total Parts (\$\$)	474.17	99.25

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	400.00	250.00
2	PANEL BEATING	New	400.00	350.00
			Gross Labour Cost (S\$)	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >