### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CS/AIG21001139/EVF3E2

AIG Building, 78 Shenton Way #07-16

Singapore 079120 Date: 12/04/2021

**REFERENCE** 

Insured/Claimant: SEE WEN LI, WENDY Policy No: 1900017778

Date of Loss: 24/01/2021 Nature of Claim: OD Claim No: 3149087690SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMJ5250E

 Make & Model:
 KIA STONIC, 998cc (A)
 Engine No:
 G3LCJP150674

 Reg. Date:
 11/03/2019 (Man. Year: 2018)
 Chassis No:
 KNAD6811VK6252744

Colour: Grey Odometer: 28466 km

Engine Capacity: 998 cc
Market Value/New Car Price: \$\$73,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Kumho 4 mm Rear Left Side: Kumho 4 mm
Front Right Side: Kumho 4 mm
Rear Right Side: Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,373.60	1,217.60	1,156.00	48.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,690.00	2,810.00	1,880.00	40.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,063.60	4,027.60	3,036.00	42.98
+ GST 7.00/7.00% (S\$)	494.45	281.93	212.52	42.98
Nett Amount (S\$)	7,558.05	4,309.53	3,248.52	42.98

**INSPECTION** 

Date of Assignment: 25/01/2021

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)

Date Inspected: 25/01/2021 Inspected At: 209 Pandan Gardens

209 Pandan Gardens Singapore 609339

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

# **Recommended Parts**

NO.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*COVER-RR BUMPER LWR	Cut	366.00 FL	*366.00 FL
3	1		*BRACKET ASSY-RR BUMPER SIDE, LH	Not Necessary	27.00 FL	*- FL
4	1		*GARNISH-QTR SIDE, LH	Cut	50.00 FL	*50.00 FL
5	1		*MOULDING ASSY-SIDE SILL, LH	Cut	248.00 FL	*248.00 FL
3	1		*GARNISH ASSY-RR DR SIDE LH	Cut	92.00 FL	*92.00 FL
7	1		*GARNISH ASSY-FRT DR SIDE, LH	Cut	82.00 FL	*82.00 FL
3	1		*GARNISH ASSY-FNDR SIDE, LH	Not Necessary	45.00 FL	*- FL
9	1		*MIRROR ASSY, OUTSIDE RR VIEW, LH	Not Necessary	585.00 FL	*- FL
10	1		*PANEL ASSY-REAR DOOR, LH	Repair	768.00 FL	*- FL
11	1		*BLACK TAPE-RR DR FR, LH	Not Necessary	13.00 FL	*- FL
12	1		*BLACK TAPE-RR DR FRAME UPR, LH	Not Necessary	7.00 FL	*- FL
13	1		*WHEEL ASSY-ALUMINIUM LHR	Cut	659.00 FL	*659.00 FL
==Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	2,962.00	1,517.00
	- List Item Discount on L Items 20.00/20.00% (S\$)			588.40	299.40	
				Total Parts (S\$)	2,373.60	1,217.60

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# **Recommended Labour**

ır Items			
SUPPLY LHR TYRE - KUMHO ECOWING ES01 185/65R14	New	380.00	360.00
RENEW LHR DOOR & RR BUMPER. REPAIR LHF FENDER, LHF DOOR & LHF FENDER	New	2,000.00	1,000.00
RESPRAY LHF FENDER, LH WINGMIRROR, LHF DOOR, LHR DOOR, LHR FENDER & LHR BUMPER	New	1,750.00	1,050.00
REMOVE & REFIT LHR DOOR COMPONENT	New	120.00	0.00
RENEW LHR SPORT RIM & TYRE	New	30.00	30.00
CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
REMOVE & REFIT REVERSE SENSOR Supplementary)	New	60.00	60.00
Gross Labou	ır Cost (S\$)	4,690.00	2,810.00
	RENEW LHR DOOR & RR BUMPER. REPAIR LHF FENDER, LHF DOOR & LHF FENDER RESPRAY LHF FENDER, LH WINGMIRROR, LHF DOOR, LHR DOOR, LHR FENDER & LHR BUMPER REMOVE & REFIT LHR DOOR COMPONENT RENEW LHR SPORT RIM & TYRE CHECK WIRING ELECTRICAL SYSTEM TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST JSING HI-SCAN PRO TEST JSING HI-SCAN PRO TEST TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT APPLY ANTI CORROSION ON AFFECTED AREAS REMOVE & REFIT REVERSE SENSOR Supplementary)	RENEW LHR DOOR & RR BUMPER. REPAIR LHF FENDER, LHF DOOR & LHF FENDER RESPRAY LHF FENDER, LH WINGMIRROR, LHF DOOR, LHR DOOR, LHR FENDER & LHR BUMPER REMOVE & REFIT LHR DOOR COMPONENT RENEW LHR SPORT RIM & TYRE CHECK WIRING ELECTRICAL SYSTEM New TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT New REMOVE & REFIT REVERSE SENSOR New	RENEW LHR DOOR & RR BUMPER. REPAIR LHF FENDER, LHF DOOR & LHF FENDER RESPRAY LHF FENDER, LH WINGMIRROR, LHF DOOR, LHR DOOR, LHR FENDER & LHR BUMPER REMOVE & REFIT LHR DOOR COMPONENT New 120.00 RENEW LHR SPORT RIM & TYRE New 30.00 CHECK WIRING ELECTRICAL SYSTEM New 30.00 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT New 120.00 APPLY ANTI CORROSION ON AFFECTED AREAS New 80.00 REMOVE & REFIT REVERSE SENSOR New 60.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.