



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2104503

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 28/06/2021
Reference CC6/CTI21001141/Ues3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SGU 2594X
Insured Veh. GT 2211G
Claim No. SNM21D200474/C02
Policy No. DMCVSNA00024152001
Accident Date 22/01/2021
Inspection Date 25/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21001141/Ues3q2	
			Date: 28/06/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GT 2211G	Veh. Inspected	SGU 2594X	
Policy No.	DMCVSNA00024152001	Coverage (\$)	0.00	
Claim No.	SNM21D200474/C02	Excess (\$)	0.00	
Assign From		Assign Date	25/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ISIS (A)	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	ZNM100038676	Colour	SILVER	
Odometer	152252 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DUNLOP	6 mm	
L/H Front Tyre	195/65 R15	DUNLOP	6 mm	
R/H Rear Tyre	195/65 R15	DUNLOP	6 mm	
L/H Rear Tyre	195/65 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/01/2021	Inspection Date	25/01/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 2594X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN MOULDING	NECESSARY	88.20	-
1	REAR WINDSCREEN	NOT NECESSARY	1,650.00	-
1	TAILGATE	BADLY DENTED	1,100.90	1,090.10
1	TAILGATE OUTER GARNISH	CRACKED	315.20	311.20
2	TAILGATE DAMPERS @\$299.10	NOT NECESSARY	598.20	-
1	TAILGATE REAR LOGO	NECESSARY	32.50	32.50
1	TAILGATE INNER LOCK	DENTED / SHORTED	181.90	181.90
1	TAILGATE LOCK STRIKER	NOT NECESSARY	48.60	-
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	368.20	368.20
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
1	TAILGATE INNER HANDLE HOLDER	NOT NECESSARY	32.00	-
1	TAILGATE WEATHERSTRIP	TWISTED	199.00	166.20
1	REAR BUMPER	DEFORMED	863.50	755.10
2	REAR BUMPER LAMPS @\$395.10	N/S CRACKED	790.20	320.50
1	REAR BUMPER TOWING COVER	DEFORMED	80.00	45.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER BRACKET N/S	DENTED	312.00	105.10
2	REAR BUMPER SIDE RETAINERS @\$45.00	NOT NECESSARY	90.00	-
1	REAR END PANEL	DENTED / BENT	517.00	517.00
1	REAR END PANEL TOP GARNISH	TWISTED	188.00	188.00
2	TAILLAMPS @\$685.00	NOT NECESSARY	1,370.00	-
2	TAILLAMP HOUSING PANELS @\$350.00	TO REPAIR SEE LABOUR	700.00	-
1	REAR FLOOR SIDE N/S PANEL	TO REPAIR SEE LABOUR	399.20	-
1	REAR FLOOR PANEL	NOT NECESSARY	1,330.20	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	326.50	-
1	REAR FLOOR PANEL TOOLS SPONGE	NOT NECESSARY	688.00	-
1	REAR LOCK SENSOR	NOT NECESSARY	295.00	-
2	REAR FENDERS @\$991.00	TO REPAIR SEE LABOUR	1,982.00	-

Report Ref No. CC6/CTI21001141/Ues3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER INNER TRIMS @\$450.00	NOT NECESSARY	900.00	-
2	REAR FENDER UNDER COVERS @\$299.20	NOT NECESSARY	598.40	-
1	REAR EXHAUST	NOT NECESSARY	785.20	-
2	REAR EXHAUST MOUNTINGS @\$45.00	NOT NECESSARY	90.00	-
1	REAR EXHAUST HEATSHIELD	NOT NECESSARY	188.90	-
1	REAR WIPER ARM	NOT NECESSARY	166.50	-
1	REAR WIPER MOTOR	NOT NECESSARY	688.90	-
1	REAR WIPER BLADE	NOT NECESSARY	88.60	-
1	REAR AXLE BEAM	NOT NECESSARY	1,650.00	-
2	REAR SHOCK ABSORBERS @\$305.10	NOT NECESSARY	610.20	-
2	REAR WHEEL HUB BEARINGS @\$450.00	NOT NECESSARY	900.00	-
1	REAR WHEEL HOUSING PANEL N/S	NOT NECESSARY	1,080.20	-
1	BONNET	BUCKLED	915.00	685.10
2	BONNET HINGES @\$151.00	BENT	302.00	130.00
1	BONNET INSULATOR	DISTORTED	285.20	282.10
1	SET BONNET INSULATOR CLIPS	NECESSARY	50.00	50.00
1	BONNET INNER RUBBER	NECESSARY	65.00	48.20
1	BONNET LOCK	TWISTED	135.50	135.50
1	BONNET LOCK CABLE	NOT NECESSARY	199.00	-
1	FRONT BUMPER	DISTORTED	950.00	945.10
2	FRONT BUMPER SPONGES @\$100.00	TORN	200.00	170.00
1	FRONT BUMPER REINFORCEMENT	DISTORTED	480.00	299.10
2	FRONT BUMPER SIDE RETAINERS @\$65.00	BENT	130.00	130.00
1	FRONT BUMPER CENTRE GRILLE	TORN	399.00	166.20
2	FRONT BUMPER FOG LAMP COVERS @\$180.00	NOT NECESSARY	360.00	-
1	FRONT BUMPER UNDER COVER	NOT NECESSARY	315.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER TOW COVER	NOT NECESSARY	30.00	-
1	FRONT GRILLE	BROKEN	525.00	466.20
1	FRONT GRILLE OUTER GARNISH	BROKEN	548.00	285.30
1	FRONT GRILLE LOGO	NECESSARY	48.00	48.00
2	HEADLAMPS @\$2950.00	CRACKED	5,900.00	2,500.00
2	HEADLAMP TOP PANELS @\$145.00	BENT	290.00	290.00

Report Ref No. CC6/CTI21001141/Ues3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SUPPORT PANEL	DISTORTED	745.00	725.10
1	FRONT SUPPORT PANEL TOP GARNISH	NOT FITTED	322.00	-
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	NOT NECESSARY	30.00	-
2	FRONT FENDERS @\$688.20	N/S TO REPAIR SEE LABOUR / O/S BUCKLED	1,376.40	688.20
2	FRONT FENDER INNER SHIELDS @\$166.50	NOT NECESSARY	333.00	-
1	FRONT BRACE PANEL	DISTORTED	290.00	161.00
1	AIR CON CONDENSER	DISTORTED	1,569.00	1,569.00
1	AIR CON DISCHARGE HOSE	NOT NECESSARY	385.10	-
1	AIR CON SUCTION HOSE	NOT NECESSARY	299.90	-
2	AIR CON CONDENSER SIDE GARNISHES @\$155.20	NOT FITTED	310.40	-
1	RADIATOR	DISTORTED	1,817.90	1,810.10
1	RADIATOR FAN ASSY	CRACKED / JAMMED	1,245.00	950.50
2	HORN UNITS @\$108.00	BENT (1 PCS ONLY)	216.00	108.00
1	AIR INTAKE MANIFOLD	NOT NECESSARY	1,800.00	-
1	FRONT LOCK CENTRE BRACKER	BENT	115.00	115.00
1	ALTERNATOR	CRACKED	1,550.10	1,485.10
1	COMPRESSEOR	SERVICEABLE	2,018.90	-
1	ABS PUMP	SERVICEABLE	3,650.20	-
1	ABS PUMP WIRE ASSY	CRACKED	1,980.10	1,880.00
1	AIR DUCT	NOT NECESSARY	215.00	-
1	AIR CLEANER BOX	NOT NECESSARY	650.20	-
1	FRONT WIPER GARNISH	NOT NECESSARY	388.00	-
1	BATTERY TRAY	NOT NECESSARY	145.90	-
1	WASHER TANK	NOT NECESSARY	245.80	-
	LESS 25% DISCOUNT		-	-5,088.40
			56,268.80	15,265.20
	<u>SPECIAL NETT ITEMS</u>			
1	REAR LICENCE PLATE W/HOLDER (SN)	SERVICEABLE	50.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	SET REAR WINDSCREEN SOLAR FILM (SN)	NOT NECESSARY	280.00	-
1	SET REAR REVERSE CAMERA (SN)	NOT NECESSARY	380.00	-

Report Ref No. CC6/CTI21001141/Ues3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR REVERSE VIDEO CAM (SN)	NOT NECESSARY	450.00	-
1	REAR LICENCE PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	200.00	-
1	FRONT LICENCE PLATE W/HOLDER (SN)	BROKEN	50.00	40.00
1	BOL RADIATOR COOLANT (SN)	NECESSARY	50.00	30.00
			1,890.00	360.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		80.00	30.00
	TO DISMANTLE & REPLACED REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REPLACED REAR WINDSCREEN .		150.00	120.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY .		120.00	80.00
	TO DISMANTLE & REPLACED ROOF LINING .	NOT NECESSARY	380.00	-
	TO DISMANTLE & REFIX REAR EXHAUST .	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX PETROL TANK .	NOT NECESSARY	100.00	-
	TO DISMANTLE & REPLACED ABS PUMP WIRE .		180.00	80.00
	TO CONDUCT WHEEL ALIGNMENT .	NOT NECESSARY	120.00	-
	TO DISMANTLE & REFIX REAR UNDER CARRIAGE.	NOT NECESSARY	380.00	-
	TO MOUNT VEHICLE ON CAR O-LINER .	NOT NECESSARY	380.00	-
	TO SPRAY RUST PROOFING .		280.00	120.00
	TO REFILL AIR CON GAS.		120.00	100.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMP HOUSING PANELS,REAR FLOOR SIDE N/S PANEL,REAR FENDERS AND FRONT FENDERS N/S.		4,800.00	1,500.00
	TO PUTTY & SPRAY PAINTING .		3,000.00	1,800.00
			10,270.00	3,880.00
GRAND TOTAL			68,428.80	19,505.20

Report Ref No. CC6/CTI21001141/Ues3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			15,000.00
---	--	--	------------------

Report Ref No. CC6/CTI21001141/Ues3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGU 2594X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGU 2594X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGU 2594X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

